



## Product Change Notification

Current Date: 24-May-2020

## TE Connectivity

Product Change Notification: P-20-019041

PCN Date: 07-MAY-20

Customer: Future Electronics(0000080100)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

## General Product Description:

Universal MATE-N-LOK

## Description of Changes

Manufacturing location change.

## Reason for Changes:

Dear Customer, In effort to assure uninterrupted delivery, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

## Estimated Dates:

|  |  |
|--|--|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only):             |
|  | 14-MAY-2020  |
| Last Ship Date (Obsolete Parts Only):  | Last Date for Mixed Shipments: (Changed Parts Only): |
|  | No Mixed Shipments                                   |

## Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |
| <a href="#">1-480708-9</a> | NO                        |                  |                      |   |                        |                                 |                           |
| <a href="#">350735-1</a>   | NO                        |                  |                      | "946668-000", "AMPS-0-0350735-1"  |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

Customer: Future Electronics Ltd ( 1273129 )

Location: Egham

Agreement Number: Agreement Unknown

## Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  | 1-480698-0-LF        | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  | 1-480708-0-LF        | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |
| <a href="#">350735-1</a>   | NO                        |                  | 350735-1-LF          | "946668-000", "AMPS-0-0350735-1"  |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  | 350777-1-LF          | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

Customer: Future Electronics Inc ( 1433287 )

Location: Bolton

Agreement Number: Agreement Unknown

## Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
|-------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |

Customer: Future Electronics Asia Pacific ( 2923061 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |

Customer: Future Electronics Inc. ( 1319888 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

Customer: Future Electronics Inc. ( 2883079 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

Customer: Future Electronics Inc. ( 1319888 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

| Part Number              | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)                          | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">350777-1</a> | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000" |                        |                                 |                           |

Customer: Future Electronics Inc ( 1290208 )

Location: Southaven

Agreement Number: FUTAGR001

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |
| <a href="#">1-480708-9</a> | NO                        |                  |                      |   |                        |                                 |                           |
| <a href="#">350735-1</a>   | NO                        |                  |                      | "946668-000", "AMPS-0-0350735-1"  |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

Customer: Future Electronics UK ( 2833922 )

Location: Hayes

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

Customer: Future Electronics EDC Services ( 2944409 )

Location: Leipzig

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)                          | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"              |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000" |                        |                                 |                           |

Customer: Future Electronics Inc. ( 2883079 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  |                      | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

Customer: Future Electronics Ltd ( 2895038 )

Location: Leipzig

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  | 1-480698-0-LF        | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  | 1-480708-0-LF        | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |
| <a href="#">350735-1</a>   | NO                        |                  | 350735-1-LF          | "946668-000", "AMPS-0-0350735-1"  |                        |                                 |                           |
| <a href="#">350777-1</a>   | NO                        |                  | 350777-1-LF          | "403311533", "AMPS-0-0350777-1", "C55004-000"   |                        |                                 |                           |

Customer: Future Electronics Inc ( 184927 )

Location: Pointe Claire

Agreement Number: FUTAGR002

Part Number(s) being Modified:

| Part Number                | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s)  | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| <a href="#">1-480698-0</a> | NO                        |                  |                      | "834930-000", "AMPS-1-0480698-0", "1-0480698-0", "4-27051-2000", "2-42932-9341", "BACA-AMP-150" |                        |                                 |                           |
| <a href="#">1-480708-0</a> | NO                        |                  |                      | "CM3789-000", "SIML-1-0480708-0"  |                        |                                 |                           |