

Automation

News

Announcement of products scheduled for discontinuation in 2020 and 2021

We would like to inform you of the product discontinuation below.

■ Discontinue products in 2020

(Last time buy end of September 2020)

Relays	Page 2
Connectors	Page 2

■ Discontinue products in 2021

(Last time buy end of March 2021)

Relays	Page 3
Switches	Page 3
Connectors	Page 4



(Last time buy end of September 2021)

Relays	Page 5
Switches	Page 7

Note: There may be delays in the updating of our website catalog with information about discontinued items.


■ Discontinue products in September 2020

• Relays

Product name	Types	Part No.	Substituted products name	Substituted part No.	Reason and remarks	Last time buy
HN relay 	All products	AHN*****	None	None	Lower customer demand caused by decreasing of market needs	End of September 2020
HN relay terminal socket 	All products	AHNA***	None	None	Lower customer demand caused by decreasing of market needs	End of September 2020

Note: Special order products and set products related to the above products are scheduled to be discontinued at the same time.


• Connectors

Products name	Types	Part No.	Substituted products name	Substituted part No.	Reason and remarks	Last time buy
Active optical connectors 	Bi-direction, 1 channel Transmission rate 20 Mbps to 6 Gbps/ch	AYG4V10565M1	Active optical connectors Bi-direction, 1 channel Transmission rate 20 Mbps to 8 Gbps/ch	AYG4V10585M1	To unify product type	End of September 2020
		AYG4V15065M1		AYG4V15085M1		
		AYG4V1A065M1		AYG4V1A085M1		
		AYG4V10565M3		AYG4V10585M3		
		AYG4V15065M3		AYG4V15085M3		
		AYG4V1A065M3		AYG4V1A085M3		

Note: Special order products and set products related to the above products are scheduled to be discontinued at the same time.



■ Discontinue products in March 2021

• Relays

Product name	Types	Part No.	Substituted products name	Substituted part No.	Reason and remarks	Last time buy
RD Coaxial SW 	SP6T (With termination)	ARD3****Z*	None	None	Due to reduced market demand for this product with no anticipated increase	End of March 2021

Note: Special order products and set products related to the above products are scheduled to be discontinued at the same time.







• Switches

Product name	Types	Part No.	Substituted products name	Substituted part No.	Reason and remarks	Last time buy
Door Interlock Switches GX Switches 	All types	AGX****	None	None	Due to reduced market demand for this product with no anticipated increase	End of March 2021
Door Interlock Switches GW Switches 	All types	AV1****	None	None	Due to reduced market demand for this product with no anticipated increase	End of March 2021

Note: Special order products and set products related to the above products are scheduled to be discontinued at the same time.

■ Discontinue products in March 2021







• Connectors

Product name	Types	Part No.	Substituted products name	Substituted part No.	Reason and remarks	Last time buy
High Current Connectors For board-to-FPC S35H (0.35mm pitch) 	All types	AXF5B**** (Socket) AXF6B**** (Header)	None	None	Due to reduced market demand for this product with no anticipated increase	End of March 2021
Narrow Pitch Connectors For board-to-FPC A35US (0.35mm pitch) 	All types	AXG7***** (Socket) AXG8***** (Header)	High Current Connectors For board-to-FPC A35UH (0.35mm pitch)	AXF5D**** (Socket) AXF6D**** (Header)	Due to reduced market demand for this product with no anticipated increase	End of March 2021
Narrow Pitch Connectors For board-to-FPC/For board-to-board P35S (0.35mm pitch) 	All types	AXT1***** (Socket) AXT2***** (Header)	Narrow Pitch Connectors For board-to-FPC/ For board-to-board P4S (0.4mm pitch)	AXT3***** (Socket) AXT4***** (Header)	Due to reduced market demand for this product with no anticipated increase	End of March 2021
FPC/FFC Connectors For FPC Y2B (0.2mm pitch) 	All types	AYF21****	FPC/FFC Connectors For FPC/FFC Y3B (0.3mm pitch)	AYF33****	Due to reduced market demand for this product with no anticipated increase	End of March 2021
FPC/FFC Connectors For FPC Y3BL (0.3mm pitch) 	All types	AYF35****	FPC/FFC Connectors For FPC/FFC Y3B (0.3mm pitch)	AYF33****	Due to reduced market demand for this product with no anticipated increase	End of March 2021
FPC/FFC Connectors For FPC/FFC Y4BH (0.4mm pitch) 	All types	AYF4*****	FPC/FFC Connectors For FPC/FFC Y5BH (0.5mm pitch)	AYF56****	Due to reduced market demand for this product with no anticipated increase	End of March 2021

Note: Special order products and set products related to the above products are scheduled to be discontinued at the same time.

■ Discontinue products in September 2021

• Relays










Product name	Types	Part No.	Substituted products name	Substituted part No.	Reason and remarks	Last time buy
DS relays 	2 poles type	DS2E-*.**-DC**V (AG2*2*)	None	None	Low demand and difficult to make operation in black ink. Production equipment became deteriorated and difficult to maintain in good condition.	End of September 2021
DS2Y relays 	All types	DS2Y-S-DC**V (AGY23**)	None	None	Low demand and difficult to make operation in black ink. Production equipment became deteriorated and difficult to maintain in good condition.	End of September 2021
RV Coaxial SW 	All types	ARV*****	None	None	Due to reduced market demand for this product with no anticipated increase	End of September 2021
RE relays 	All types	ARE1*****	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
JS/JS-M relays * 	All types	JS1***.***V-F*.** (AJS*****F*) JSM1*.***V.* (AJSM***)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
JQ relays 	All types	JQ1**.***V-F (AJQ*34***F)	LQ relays	ALQ***	To unify product type to LQ relays	End of September 2021

Note: Special order products and set products related to the above products are scheduled to be discontinued at the same time.

* Made in Japan JS&JSM relays became discontinued in 2019.

■ Discontinue products in September 2021


• Relays

Product name	Types	Part No.	Substituted products name	Substituted part No.	Reason and remarks	Last time buy
JT-V relays 	All types	JTV1**-***-**V (AJTV***)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
JT-N relays 	All types	JTN1**-***-F-DC**V (AJT*****)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
LE relays 	All types	ALE*P***	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
LK-T relays 	All types	LKT1aF-**V (ALKT32*)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
LK-Q relays 	All types	LKQ1aF-**V-TV* (ALKQ32**)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
LK-G relays 	All types	LKG1aF-**V-*** (ALKG*2**)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
LK-P relays 	All types	LKP1aF-**V (ALKP32*)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
PQ relays 	All types	PQ1a-**V (APQ331*)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021
PQ relays socket 	All types	PC1a-PS (APC3801)	None	None	Low demand and difficult to make operation in black ink.	End of September 2021

Note: Special order products and set products related to the above products are scheduled to be discontinued at the same time.

■ Discontinue products in September 2021

• Switches

Product name	Types	Part No.	Substituted products name	Substituted part No.	Reason and remarks	Last time buy
Light Touch Switches 3.0mm×2.6mm 2 terminals SMD 	All types	EVPBA****	Light Touch Switches 3.0mm×2.0mm SMD	EVPAW	Due to reduced market demand	End of September 2021

Note: Special order products and set products related to the above products are scheduled to be discontinued at the same time.

MPN's Affected

DS2E-S-DC12V
DS2E-S-DC5V
DS2E-SL2-DC12V
DS2E-SL2-DC24V
JS1-12V-F
JS1-24V-F
JS1-5V-F
JS1-9V-F
JS1F-B-48V-F
JSM1-12V-5
JSM1A-12V-5
JTN1AS-PA-F-DC12V
JTN1AS-PA-F-DC18V
JTN1AS-PA-F-DC24V
JTN1S-TMP-F-DC12V
LKP1AF-12V
DS2E-S-DC5V
DS2E-SL2-DC12V
DS2E-SL2-DC24V / AG2
JS1-12V-F
JS1-24V-F
JS1-9V-F
JS1A-12V-F
JSM1-12V-5
JSM1A-12V-5
JTN1AS-PA-F-DC12V
JTN1AS-PA-F-DC18V
JTN1AS-PA-F-DC24V
JTN1S-TMP-F-DC12V