

# Product / Process Change Notification



N° 2020-108-A

Dear Customer,

Please find attached our INFINEON Technologies PCN:

## Introduction of an additional final test location for DSO 150 mils package

Important information for your attention:

- Please respond to this PCN by indicating your decision on the approval form, sign it and return to your sales partner before **19 January 2021**.
- Infineon aligns with the widely-recognized JEDEC STANDARD "JESD46", which stipulates:  
"Lack of acknowledgement of the PCN within 30 days constitutes acceptance of the change."

Your prompt reply will help Infineon Technologies to assure a smooth and well executed transition. If Infineon does not hear from your side by the due date, we will assume your full acceptance to this proposed change and its implementation.

Your attention and response to this matter is greatly appreciated.

Infineon Technologies AG  
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0  
Chairman of the Supervisory Board: Dr. Wolfgang Eder  
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider  
Registered Office: Neubiberg  
Commercial Register: München HRB 126492

# Product / Process Change Notification



N° 2020-108-A

► **Products affected:** Please refer to attached affected product list 1\_cip20108\_A

► **Detailed Change Information:**

**Subject:** Introduction of an additional final test location for DSO 150 mils package

**Reason:** Enabling Infineon Technologies Asia Pacific Pte. Ltd., Singapore, Singapore and Infineon Technologies Batam P.T., Batam, Indonesia as Multi Testing Sites.

| <b>Description:</b>        | <b><u>Old</u></b>   | <b><u>New</u></b>   |
|----------------------------|---|---|
| <b>Final Test Location</b> | Product dependent: <ul style="list-style-type: none"><li>• Infineon Technologies Asia Pacific Pte. Ltd., Singapore, Singapore</li></ul> or <ul style="list-style-type: none"><li>• Infineon Technologies Batam P.T., Batam, Indonesia</li></ul> | All products: multi-site strategy <ul style="list-style-type: none"><li>• Infineon Technologies Asia Pacific Pte. Ltd., Singapore, Singapore</li></ul> and <ul style="list-style-type: none"><li>• Infineon Technologies Batam P.T., Batam, Indonesia</li></ul> |

► **Product Identification:** Traceability assured via internal part number.  
No change in SP ordering number.

► **Impact of Change:** No impact on electrical performance, quality and reliability expected. Verified by test correlation studies on reference products.  
No change in fit, form and function expected.

► **Attachments:** Affected product list 1\_cip20108\_A

► **Time Schedule:**

- Final qualification report: available
- First samples available: on request
- Intended start of delivery: 03-2020 or earlier after customer approval

If you have any questions, please do not hesitate to contact your local Sales office.



| Sales name    | SP number   | OPN                | Package      |
|---------------|-------------|--------------------|--------------|
| 2EDF7175F     | SP002447628 | 2EDF7175FXUMA1     | PG-DSO-16-11 |
| 2EDF7175F     | SP005416294 | 2EDF7175FXUMA2     | PG-DSO-16    |
| 2EDF7275F     | SP001698294 | 2EDF7275FXUMA1     | PG-DSO-16-11 |
| 2EDF7275F     | SP005416293 | 2EDF7275FXUMA2     | PG-DSO-16-11 |
| 2EDN7223F     | SP001617304 | 2EDN7223FXTMA1     | PG-DSO-8     |
| 2EDN7224F     | SP001617308 | 2EDN7224FXTMA1     | PG-DSO-8     |
| 2EDN7424F     | SP001648594 | 2EDN7424FXTMA1     | PG-DSO-8     |
| 2EDN7523F     | SP001358244 | 2EDN7523FXTMA1     | PG-DSO-8     |
| 2EDN7524F     | SP001339264 | 2EDN7524FXTMA1     | PG-DSO-8     |
| 2EDN8523F     | SP001412642 | 2EDN8523FXTMA1     | PG-DSO-8     |
| 2EDN8524F     | SP001412648 | 2EDN8524FXTMA1     | PG-DSO-8     |
| CM01-C        | SP001584334 | CM01CXUMA1         | PG-DSO-8     |
| DP2A11-A      | SP001276874 | DP2A11AXUMA1       | PG-DSO-8     |
| HDPLSB        | SP002797968 | HDPLSBXUMA1        | PG-DSO-16    |
| HDPLSC        | SP005349861 | HDPLSCXUMA1        | PG-DSO-16    |
| ICB2FL03G     | SP001228884 | ICB2FL03GXUMA2     | PG-DSO-16    |
| ICE1HS01G-1   | SP001077176 | ICE1HS01G1XUMA1    | PG-DSO-8-13  |
| ICE1PCS01G    | SP000717646 | ICE1PCS01GFUMA1    | PG-DSO-8     |
| ICE1PCS02G    | SP000717648 | ICE1PCS02GXUMA1    | PG-DSO-8     |
| ICE2PCS03G    | SP000718526 | ICE2PCS03GXUMA1    | PG-DSO-8     |
| ICE2QR0665G   | SP000907678 | ICE2QR0665GXUMA1   | PG-DSO-12    |
| ICE2QR1080G   | SP001421194 | ICE2QR1080GXUMA1   | PG-DSO-12    |
| ICE2QR1765G   | SP000905550 | ICE2QR1765GXUMA1   | PG-DSO-12    |
| ICE2QR2280G   | SP000775242 | ICE2QR2280GXUMA1   | PG-DSO-12    |
| ICE2QR2280G-1 | SP001087212 | ICE2QR2280G1XUMA1  | PG-DSO-12    |
| ICE2QR4765G   | SP000907668 | ICE2QR4765GXUMA1   | PG-DSO-12    |
| ICE2QR4780G   | SP001421156 | ICE2QR4780GXUMA2   | PG-DSO-12    |
| ICE2QS02G     | SP000718534 | ICE2QS02GXUMA1     | PG-DSO-8     |
| ICE2QS03G     | SP000775042 | ICE2QS03GXUMA1     | PG-DSO-8     |
| ICE3AR1080JG  | SP001421218 | ICE3AR1080JGXUMA1  | PG-DSO-12    |
| ICE3AR2280JG  | SP001421210 | ICE3AR2280JGXUMA1  | PG-DSO-12    |
| ICE3AR4780JG  | SP001421204 | ICE3AR4780JGXUMA1  | PG-DSO-12    |
| ICE3AS03LJG   | SP000783724 | ICE3AS03LJGXUMA1   | PG-DSO-8     |
| ICE3B0565JG   | SP000077217 | ICE3B0565JGXUMA1   | PG-DSO-12    |
| ICE3BR4765JG  | SP000716242 | ICE3BR4765JGXUMA1  | PG-DSO-12    |
| ICE3BS03LJG   | SP000783726 | ICE3BS03LJGXUMA1   | PG-DSO-8     |
| ICE3GS03LJG   | SP000812044 | ICE3GS03LJGXUMA1   | PG-DSO-8     |
| ICE3PCS01G    | SP000639560 | ICE3PCS01GXUMA1    | PG-DSO-14    |
| ICE3PCS02G    | SP000639564 | ICE3PCS02GXUMA1    | PG-DSO-8     |
| ICE3PCS02G    | SP000972498 | ICE3PCS02GXUMA2    | PG-DSO-8     |
| ICE3PCS03G    | SP000639568 | ICE3PCS03GXUMA1    | PG-DSO-8     |
| ICE3RBR0665JG | SP001421274 | ICE3RBR0665JGXUMA1 | PG-DSO-12    |
| ICE3RBR1765JG | SP001421232 | ICE3RBR1765JGXUMA1 | PG-DSO-12    |
| ICE3RBR4765JG | SP001421226 | ICE3RBR4765JGXUMA1 | PG-DSO-12    |
| ICL5101       | SP001213622 | ICL5101XUMA1       | PG-DSO-16    |
| ICL5102       | SP002224374 | ICL5102XUMA2       | PG-DSO-16    |
| ICL8001G      | SP000773086 | ICL8001GXUMA1      | PG-DSO-8     |
| ICL8002G      | SP000923986 | ICL8002GXUMA1      | PG-DSO-8     |
| IDP2105       | SP001673222 | IDP2105XUMA1       | PG-DSO-12    |
| IDP2301       | SP001368356 | IDP2301XUMA1       | PG-DSO-16    |
| IDP2301-3     | SP001600872 | IDP23013XUMA1      | PG-DSO-16    |
| IDP2303       | SP001618956 | IDP2303XUMA1       | PG-DSO-16    |



| Sales name       | SP number   | OPN                 | Package     |
|------------------|-------------|---------------------|-------------|
| IDP2303A         | SP001618966 | IDP2303AXUMA1       | PG-DSO-16   |
| IDP2308          | SP001721614 | IDP2308XUMA1        | PG-DSO-14   |
| IDP2308H         | SP004038024 | IDP2308HXUMA1       | PG-DSO-14   |
| IDP2308S         | SP004231976 | IDP2308SXUMA1       | PG-DSO-14   |
| IDP2308T1        | SP002124966 | IDP2308T1XUMA1      | PG-DSO-14   |
| IDP2322          | SP001669912 | IDP2322XUMA1        | PG-DSO-16   |
| ILD2111          | SP001415548 | ILD2111XUMA2        | PG-DSO-8    |
| ILD6070          | SP000955324 | ILD6070XUMA1        | PG-DSO-8-27 |
| ILD6150          | SP000955332 | ILD6150XUMA1        | PG-DSO-8-27 |
| ILD8150          | SP001805682 | ILD8150XUMA1        | PG-DSO-8    |
| ILD8150E         | SP001805686 | ILD8150EXUMA1       | PG-DSO-8    |
| LTA1605A         | SP001601660 | LTA1605AXUMA1       | PG-DSO-16   |
| LTA1605B         | SP001619826 | LTA1605BXUMA1       | PG-DSO-16   |
| LTA1605C         | SP001669920 | LTA1605CXUMA1       | PG-DSO-16   |
| LTA1605D         | SP005403449 | LTA1605DXUMA2       | PG-DSO-16   |
| LTA1806A         | SP004038286 | LTA1806AXUMA1       | PG-DSO-14   |
| LTA1806B         | SP005347658 | LTA1806BXUMA1       | PG-DSO-14   |
| MDP16            | SP001368438 | MDP16XUMA1          | PG-DSO-16   |
| MDP16            | SP001783660 | MDP16XUMA2          | PG-DSO-16   |
| MDP16R           | SP001696496 | MDP16RXUMA1         | PG-DSO-16   |
| MDP16R           | SP001994520 | MDP16RXUMA2         | PG-DSO-16   |
| OS2614353        | SP000854608 | OS2614353XUMA1      | PG-DSO-16   |
| S007G GEG 600997 | SP005354842 | S007GGEG600997XUMA2 | P-DSO-16    |
| S007G GEG 601095 | SP005354843 | S007GGEG601095XUMA2 | P-DSO-16    |
| S007G GEG 602040 | SP005354844 | S007GGEG602040XUMA2 | P-DSO-16    |
| SAE800G          | SP000697948 | SAE800GXLLA1        | PG-DSO-8    |
| SAE800G GEG      | SP000080994 | SAE800GGEGXUMA1     | PG-DSO-8    |
| SAE800G GEG      | SP000783572 | SAE800GGEGXUMA2     | PG-DSO-8    |
| SLKD338          | SP005347437 | SLKD338XUMA1        | PG-DSO-8    |
| TCA355G          | SP000697950 | TCA355GXLLA1        | PG-DSO-8    |
| TCA355G GEG      | SP000744922 | TCA355GGEGXUMA1     | PG-DSO-8    |
| TCA505BG-2       | SP005354395 | TCA505BG2XUMA1      | PG-DSO-16   |
| TDA4862G GEG     | SP000697958 | TDA4862GGEGXUMA2    | PG-DSO-8    |
| TDA4863-2G       | SP000697960 | TDA4863GXUMA2       | PG-DSO-8    |
| TDA4863G         | SP000697962 | TDA4863GXUMA2       | PG-DSO-8    |
| TLE8080-2EM      | SP001052526 | TLE80802EMXUMA1     | PG-SSOP-24  |
| TLE8080-3EM      | SP001633564 | TLE80803EMXUMA1     | PG-SSOP-24  |
| TLE8080EM        | SP000823824 | TLE8080EMXUMA1      | PG-SSOP-24  |
| TLE8088EM        | SP000685716 | TLE8088EMXUMA1      | PG-SSOP-24  |
| XDPL8105         | SP001639446 | XDPL8105XUMA1       | PG-DSO-8    |
| XDPL8210         | SP001643692 | XDPL8210XUMA1       | PG-DSO-8    |
| XDPL8218         | SP001707258 | XDPL8218XUMA1       | PG-DSO-8    |
| XDPL8218P        | SP001727928 | XDPL8218PXUMA1      | PG-DSO-8    |
| XDPL8219         | SP002990946 | XDPL8219XUMA1       | PG-DSO-8    |
| XDPL8220         | SP001398160 | XDPL8220XUMA1       | PG-DSO-16   |
| XDPL8221         | SP001684238 | XDPL8221XUMA1       | PG-DSO-16   |
| XDPS21061        | SP002251196 | XDPS21061XUMA1      | PG-DSO-12   |
| XDPS21071        | SP005355100 | XDPS21071XUMA1      | PG-DSO-12   |
| XDPS3301         | SP001683442 | XDPS3301XUMA1       | PG-DSO-14   |
| XENZ02           | SP001639438 | XENZ02XUMA1         | PG-DSO-8    |