



Expertise Applied | Answers Delivered

8755 W. Higgins Road  
Suite 500  
Chicago, IL 60631

[www.littelfuse.com](http://www.littelfuse.com)

---

To: Littelfuse Sales, Sales Support & Valued Customers

From: Littelfuse Product Management – Industrial Business Unit

Subject: OTLS Product Update To Improve Supply Base Material Breadth and Improve Appearance

Document Number: LFPCN\_PG0131

Date: Rev 03/09/2022

This notice is to inform customers of a modification that will be made to TLS fuses in order to increase the breadth of the supply base from which metal materials are available. The current element strip materials are only available from specialty suppliers. In addition, the caps will be changed to nickel plating in order to reduce appearance issues that naturally develop on the current caps over time. Please see the included file for additional details prepared by the Littelfuse Engineering team.

The effective date of this product update is expected to be Apr 29, 2022.

Also, please see attached list with part numbers affected by this modification.

Thank you for your continued business. If you have any questions, or need additional information please contact your Littelfuse representative.

Sincerely,

**Augusto Sánchez**

Product Manager

Industrial Business Unit

Littelfuse, Inc.

Office: +52 878-784-4734

Techline: +1 800-TEC-FUSE

[www.littelfuse.com/electrical](http://www.littelfuse.com/electrical)

List of Part Number with Element Material Change

TLS 70 Amps
0TLS070.SLSA
0TLS070.T
0TLS070.TXL
0TLS070.TXLB
0TLS070.TXLR
0TLS070.TXLS
0TLS070.TXLS-C
0TLS070.TXLSE
0TLS070.TXMB
0TLS070.TXV
0TLS070.ZXLBE
0TLS070.ZXLR
0TLS070.ZXLSE

TLS 80 Amps
0TLS080.SLSA
0TLS080.T
0TLS080.TXL
0TLS080.TXLB
0TLS080.TXLR
0TLS080.TXLS
0TLS080.TXLS-C
0TLS080.TXLSE
0TLS080.TXMB
0TLS080.TXV
0TLS080.ZXLBE
0TLS080.ZXLR
0TLS080.ZXLSE

TLS 100 Amps
0TLS100.SLSA
0TLS100.T
0TLS100.TXL
0TLS100.TXLB
0TLS100.TXLR
0TLS100.TXLS
0TLS100.TXLS-C
0TLS100.TXLSE
0TLS100.TXMB
0TLS100.TXV
0TLS100.ZXLBE
0TLS100.ZXLR
0TLS100.ZXLSE

List of Part Numbers with change to Nickel Plated Cap

T
0TLS001.T
0TLS002.T
0TLS003.T
0TLS005.T
0TLS006.T
0TLS010.T
0TLS015.T
0TLS020.T
0TLS025.T
0TLS030.T
0TLS035.T
0TLS040.T
0TLS050.T
0TLS060.T
0TLS070.T
0TLS080.T
0TLS090.T
0TLS100.T
0TLS110.T
0TLS125.T

TXL
0TLS001.TXL
0TLS002.TXL
0TLS003.TXL
0TLS005.TXL
0TLS006.TXL
0TLS010.TXL
0TLS015.TXL
0TLS020.TXL
0TLS025.TXL
0TLS030.TXL
0TLS035.TXL
0TLS040.TXL
0TLS050.TXL
0TLS060.TXL
0TLS070.TXL
0TLS080.TXL
0TLS090.TXL
0TLS100.TXL

TXLB
0TLS001.TXLB
0TLS002.TXLB
0TLS003.TXLB
0TLS005.TXLB
0TLS006.TXLB
0TLS010.TXLB
0TLS015.TXLB
0TLS020.TXLB
0TLS025.TXLB
0TLS030.TXLB
0TLS035.TXLB
0TLS040.TXLB
0TLS050.TXLB
0TLS060.TXLB
0TLS070.TXLB
0TLS080.TXLB
0TLS090.TXLB
0TLS100.TXLB

TLS
0TLS001.TXLS
0TLS002.TXLS
0TLS003.TXLS
0TLS005.TXLS
0TLS006.TXLS
0TLS010.TXLS
0TLS015.TXLS
0TLS020.TXLS
0TLS025.TXLS
0TLS030.TXLS
0TLS035.TXLS
0TLS040.TXLS
0TLS050.TXLS
0TLS060.TXLS
0TLS070.TXLS
0TLS080.TXLS
0TLS090.TXLS
0TLS100.TXLS

TXLS-C
0TLS001.TXLS-C
0TLS002.TXLS-C
0TLS003.TXLS-C
0TLS005.TXLS-C
0TLS006.TXLS-C
0TLS010.TXLS-C
0TLS015.TXLS-C
0TLS020.TXLS-C
0TLS025.TXLS-C
0TLS030.TXLS-C
0TLS035.TXLS-C
0TLS040.TXLS-C
0TLS050.TXLS-C
0TLS060.TXLS-C
0TLS070.TXLS-C
0TLS080.TXLS-C
0TLS090.TXLS-C
0TLS100.TXLS-C

TXMB
0TLS001.TXMB
0TLS002.TXMB
0TLS003.TXMB
0TLS005.TXMB
0TLS006.TXMB
0TLS010.TXMB
0TLS015.TXMB
0TLS020.TXMB
0TLS025.TXMB
0TLS030.TXMB
0TLS035.TXMB
0TLS040.TXMB
0TLS050.TXMB
0TLS060.TXMB
0TLS070.TXMB
0TLS080.TXMB
0TLS090.TXMB
0TLS100.TXMB

TXV
0TLS001.TXV
0TLS002.TXV
0TLS003.TXV
0TLS005.TXV
0TLS006.TXV
0TLS010.TXV
0TLS015.TXV
0TLS020.TXV
0TLS025.TXV
0TLS030.TXV
0TLS035.TXV
0TLS040.TXV
0TLS050.TXV
0TLS060.TXV
0TLS070.TXV
0TLS080.TXV
0TLS090.TXV
0TLS100.TXV

SLSA
0TLS001.SLSA
0TLS002.SLSA
0TLS003.SLSA
0TLS005.SLSA
0TLS006.SLSA
0TLS010.SLSA
0TLS015.SLSA
0TLS020.SLSA
0TLS025.SLSA
0TLS030.SLSA
0TLS035.SLSA
0TLS040.SLSA
0TLS050.SLSA
0TLS060.SLSA
0TLS070.SLSA
0TLS080.SLSA
0TLS090.SLSA
0TLS100.SLSA

TXLR
0TLS035.TXLR
0TLS040.TXLR
0TLS050.TXLR
0TLS060.TXLR
0TLS070.TXLR
0TLS080.TXLR
0TLS090.TXLR
0TLS100.TXLR
0TLS110.TXLR
0TLS125.TXLR

TXLSE
0TLS035.TXLSE
0TLS040.TXLSE
0TLS050.TXLSE
0TLS060.TXLSE
0TLS070.TXLSE
0TLS080.TXLSE
0TLS090.TXLSE
0TLS100.TXLSE
0TLS110.TXLSE
0TLS125.TXLSE

ZXLR
0TLS035.ZXLR
0TLS040.ZXLR
0TLS050.ZXLR
0TLS060.ZXLR
0TLS070.ZXLR
0TLS080.ZXLR
0TLS090.ZXLR
0TLS100.ZXLR
0TLS110.ZXLR
0TLS125.ZXLR

ZXLSE
0TLS035.ZXLSE
0TLS040.ZXLSE
0TLS050.ZXLSE
0TLS060.ZXLSE
0TLS070.ZXLSE
0TLS080.ZXLSE
0TLS090.ZXLSE
0TLS100.ZXLSE
0TLS110.ZXLSE
0TLS125.ZXLSE