

Product Change Notification

Current Date: 29-Apr-2022

PCN Date: 23-APR-22

TE Connectivity

Product Change Notification: PCN-22-136405

Customer: Future Electronics(0000080100) Location: WORLDWIDE Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

New package method

General Product Description:

8P Mod jack , SE

Description of Changes
Bulk Package to Tray Package

Current package method



Other attachments:

Drop test report

Package change from bulk package to soft tray

Reason for Changes:

Packaging improvement

PCN Attributes:		
Product Category:	Kind of Change:	
Connectors	Specification	
Change Feature:	Potential Customer Impact:	
Packaging Specification TE	No Customer Impact	
Remarks:		

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	18-JUL-2022
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>100190-2</u>	NO						

Worldwide Account Form Page 2 of 2

Customer: Future Electronics Inc (184927) Location: Pointe Claire Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
100190-2	NO						

 Customer:
 Future Electronics Inc (1290208)
 Location:
 Southaven
 Agreement Number:
 Agreement Unknown

Part Number(s) being Modified:

Part	Part Discontinued per PCN	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number		Drawing	Number	Number(s)	Number	Number(s)	Difference
100190-2	NO						



TEGT BEGORD	Title of Test ☐ Vibration ■ Free Drop Test	Test Number CPK-202204001
TEST RECORD Tyco Electronics	☐ Transportation	
AMP GUANGDONG LTD.	Tester	Date Started Date Complete
AMP GUANGDONG LTD.	Hero Cheng	13/Apr/2022 13/Apr/2022
	Checker	
	Trustin Zhang	
Requester	Test Location	Product Weight Quantity per Box
QE(Juan Wu)	Test Lab, Tyco / AMP Guangdong Ltd	4.52 kg 1260 pcs/box
Product Description	Part No No of Boxes	
PN 3-215877-1, MODULAR J	3-215877-1 1	

TEST PROCEDURE:	ISTA 1A 10kg less than ; 760mm, 10-19kg less than ;610mm
	(10 locations; 1-corner, 2-btm edge(W), 3-btm-edge(L), 4-edge(H), 5,6,7,8,9,10-6 panels)
	ISTA 2A
	10kg less than ; 970mm, 10-19kg less than ;810mm
	(10 locations; 1-corner, 2-btm edge(W), 3-btm-edge(L), 4-edge(H), 5,6,7,8,9,10-6 panels)
	109-132-2 Tyco Electronics, Test specification
	Up to 9.06kg incl.; Assurance level –1(609mm), level-2(381mm), level-3(229mm)
	(6 locations; 1-btm, 2-btm edge(W), 3-btm-edge(L),4-btm corner, 5-btm corner,6-top)
	JIS Z 0200
	Up to 10kg incl.; Assurance level –1(800mm), level-2(600mm), level-3(400mm)
	(10 locations; 1-corner, 2-btm edge(W), 3-btm-edge(L), 4-edge(H), 5,6,7,8,9,10-6 panels)

CONDITIONS:

Drop height 760 mm Temperature 26.3 degrees Humidity 60%

Box Size 380L-380W-200H (mm) RSC Box Type ☐ FOL Impact Surface Concrete floor Remarks weather : Sunny

PRODUCT DESCRIPTION:

Pkg method: 210 pcs/bag x 6 =1260 Pcs/shipping box The detail packaging instruction is according to PS 107-107766 Rev A.

- ---Test result: There are no any products damaged and defect after drop test.
- --- The corner of shipping box impacted were distorted, but not damaged

RESULTS:

Test Result: Passed □Failed

NG Ratio

0%, 0 pcs (NG) / 1260 pcs (OK) : 1 BOX



Photo






Packaging Change from bag to Soft Tray for MODULAR JACK SIDE ENTRY, 8 POS

18-Apr-2022

EVERY CONNECTION COUNTS










Change from bag to Soft Tray for MODULAR JACK SIDE ENTRY, 8 POS

Bulk in bag packaging

Soft Tray packaging



Affected PNs: 3-215877-1 and 100190-2

<u>Reason for change:- Connector Deformation may happen during transportation so changing to soft tray Package to avoid deformation.</u>

@ 2020 TE Connectivity. Confidential & Proprietary. Do not reproduce or distribute externally including non-authorized representatives and distributors. Create a sustainable future by limiting print copies, and recycling paper.