

**End-Of-Life Notice**  
 (Notification – PLC220006(R1) )  
 [Issue Date – 9/6/2022]

**To:** Our Valued Customers

**Overview:** The purpose of this notification is to communicate that Renesas Electronics has begun the End-of-Life (EOL) Process on select part numbers.

**R1: This revised notice is to correct replacement part numbers as detailed below.**

**No change to LTB date and LTS date.**

Exact Renesas Part # No other variation is being impacted.	Replacement/Similar / Re-Design
5962-8687511XA	5962-8687511YA changed to None
5962-8687515XA	5962-8687515YA changed to None
5962-9222201M2A	5962-9222201MRA changed to None
7024L55GM	7024L55GB changed to None
7025S25PFG8	7025S25PFG changed to None
7026L25GM	7026L25GB changed to None

Attached is a list of products affected by this notification.

**Affected Products:** Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

<b>Key Dates:</b>	Final Last Time Buy (LTB) Orders placed after this date will not be processed.	2/10/2023
	Last Shipment (LTS)	8/10/2023

**Response:** Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Renesas Electronics America Inc. will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Any order resulting from this notice shall be governed by Renesas’s General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Please contact your local sales representative for any questions or comments.  
 Thank you for your attention.

Sincerely,  
 Renesas Electronics

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
2308-1HPGG	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI
2308-1HPGG8	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI8
2308-1HPGGI	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI
2308-1HPGGI8	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI8
2308-2DCG	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI
2308-2DCG8	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI8
2308-2DCGI	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI
2308-2DCGI8	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI8
2308B-1HPGG	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI
2308B-1HPGG8	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI8
2308B-1HPGGI	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI
2308B-1HPGGI8	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI8
2308B-2DCG	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI
2308B-2DCG8	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI8
23S08-1HDCG	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI
23S08-1HDCG8	9/6/2022	2/10/2023	8/10/2023	2305A-1HDCGI8
252MI-32LF	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI
252MI-32LFT	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI8
290G-18LF	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI
290G-18LFT	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI8
290G-19LF	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI
290G-19LFT	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI8
290PGILF	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI
290PGILFT	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI8
54FCT162244TEB	9/6/2022	2/10/2023	8/10/2023	54FCT162244CTEB
54FCT16244ATEB	9/6/2022	2/10/2023	8/10/2023	None
54FCT16244TEB	9/6/2022	2/10/2023	8/10/2023	None
54FCT16245TEB	9/6/2022	2/10/2023	8/10/2023	None
54FCT240ATLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT240CTLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT240TLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT244CTDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT244CTLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT245CTDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT245TLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT373ATDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT373ATLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT373CTDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT373CTLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT373TLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT374ATDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT374ATLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT374CTDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT374CTLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT374TLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT573ATDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT573ATLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT573CTDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT573CTLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT573TLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT574ATLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT574CTDB	9/6/2022	2/10/2023	8/10/2023	None
54FCT574CTLB	9/6/2022	2/10/2023	8/10/2023	None
54FCT574TLB	9/6/2022	2/10/2023	8/10/2023	None
5962-3829406MZA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829407MZA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829408MZA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829411MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829412MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829413MZA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829414MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829415MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829416MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-3829416MZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687501XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687501YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687502XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687502YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687504UA	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
5962-8687504XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687505YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687506XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687506YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687507UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687507XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687507YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687508XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687508YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687509XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687510XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687511XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687511YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687512UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687512XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687513XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687514XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687515XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687515YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687516XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687516YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687521UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687521YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687522UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687522XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8687522YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700201UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700201ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700202UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700203UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700203ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700205TA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700205ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700206UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700207UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700207ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700208TA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700208UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700209UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700209ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700210UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700210ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700210ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700211UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700211ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700212UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700212ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700213ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700214UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700214ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700215UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700215ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700216UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700216ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700217UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700217ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700218TA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700218UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700220UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700221UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700221ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700222UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700222ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700223UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8700224UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8753101TA	9/6/2022	2/10/2023	8/10/2023	None
5962-8753101XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8753103TA	9/6/2022	2/10/2023	8/10/2023	None
5962-8861008ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8861010ZA	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
5962-8861011UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8861012ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866201NA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866203NA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866204XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866205XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866206XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866507ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866508ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866509ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866510ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866511UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866513ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866514ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866516UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866516ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866905YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866905ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8866906YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8874001LA	9/6/2022	2/10/2023	8/10/2023	None
5962-8874002LA	9/6/2022	2/10/2023	8/10/2023	None
5962-8953605UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8953606UA	9/6/2022	2/10/2023	8/10/2023	None
5962-8956705XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8956705ZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8956807XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8966606XA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976401MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976402MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976403MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976403MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976404MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976404MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976405MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976405MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976406MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976406MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976407MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976407MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-8976408MZA	9/6/2022	2/10/2023	8/10/2023	None
5962-8986303YA	9/6/2022	2/10/2023	8/10/2023	None
5962-8986305YA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150801MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150802MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150803MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150804MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150804MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150805MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150805MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150806MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150806MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150807MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150808MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150809MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150810MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150810MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9150812MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161701MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161702MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161702MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161703MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161703MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161704MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161704MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161705MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161705MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161706MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9161706MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166201MXA	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
5962-9166201MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166202MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166204MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166205MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166206MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166207MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166210MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166211MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9166212MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9167703MZA	9/6/2022	2/10/2023	8/10/2023	None
5962-9220303M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221301M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221303M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221305M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221401M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221405MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9221702M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221703M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221703MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9221804M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221804MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9221806M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9221806MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9222201M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9222201MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9222203M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9222205M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9222205MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9223801M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9223801MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9223802MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9223803M2A	9/6/2022	2/10/2023	8/10/2023	None
5962-9223803MRA	9/6/2022	2/10/2023	8/10/2023	None
5962-9225801MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9227101MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9227201MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9317702MXA	9/6/2022	2/10/2023	8/10/2023	None
5962-9317702MYA	9/6/2022	2/10/2023	8/10/2023	None
5962-9317703MXA	9/6/2022	2/10/2023	8/10/2023	None
5P50912DVG1	9/6/2022	2/10/2023	8/10/2023	5P35021-000NDG2
5P50912DVG18	9/6/2022	2/10/2023	8/10/2023	5P35021-000NDG28
5P50912NBG1	9/6/2022	2/10/2023	8/10/2023	5P35021-000NDG28
5P50912NBG18	9/6/2022	2/10/2023	8/10/2023	5P35021-000NDG28
5P50913NBG1	9/6/2022	2/10/2023	8/10/2023	5P35021-000NDG28
5P50913NBG18	9/6/2022	2/10/2023	8/10/2023	5P35021-000NDG28
5V49EE704NDG1	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLG1
5V49EE704NDG18	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLG18
6116LA150DB	9/6/2022	2/10/2023	8/10/2023	None
6116LA20TDB	9/6/2022	2/10/2023	8/10/2023	None
6116LA25DB	9/6/2022	2/10/2023	8/10/2023	None
6116LA25TDB	9/6/2022	2/10/2023	8/10/2023	None
6116LA35DB	9/6/2022	2/10/2023	8/10/2023	None
6116LA35TDB	9/6/2022	2/10/2023	8/10/2023	None
6116LA45DB	9/6/2022	2/10/2023	8/10/2023	None
6116LA45TDB	9/6/2022	2/10/2023	8/10/2023	None
6116LA55DB	9/6/2022	2/10/2023	8/10/2023	None
6116LA55TDB	9/6/2022	2/10/2023	8/10/2023	None
6116LA70DB	9/6/2022	2/10/2023	8/10/2023	None
6116LA70TDB	9/6/2022	2/10/2023	8/10/2023	None
6116LA90TDB	9/6/2022	2/10/2023	8/10/2023	None
6116SA120TDB	9/6/2022	2/10/2023	8/10/2023	None
6116SA150DB	9/6/2022	2/10/2023	8/10/2023	None
6116SA150TDB	9/6/2022	2/10/2023	8/10/2023	None
6116SA20DB	9/6/2022	2/10/2023	8/10/2023	None
6116SA35TDB	9/6/2022	2/10/2023	8/10/2023	None
6116SA45DB	9/6/2022	2/10/2023	8/10/2023	None
6116SA45TDB	9/6/2022	2/10/2023	8/10/2023	None
6116SA55DB	9/6/2022	2/10/2023	8/10/2023	None
6116SA70DB	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
6116SA70TDB	9/6/2022	2/10/2023	8/10/2023	None
6116SA90TDB	9/6/2022	2/10/2023	8/10/2023	None
664G-03LF	9/6/2022	2/10/2023	8/10/2023	None
664G-03LFT	9/6/2022	2/10/2023	8/10/2023	None
6P40118PGG	9/6/2022	2/10/2023	8/10/2023	None
6P40118PGG8	9/6/2022	2/10/2023	8/10/2023	None
6P49308NLG	9/6/2022	2/10/2023	8/10/2023	RC21012A000GNA#BBO
6P49308NLG8	9/6/2022	2/10/2023	8/10/2023	RC21012A000GNA#KBO
6V49198APGG	9/6/2022	2/10/2023	8/10/2023	None
6V49198APGG8	9/6/2022	2/10/2023	8/10/2023	None
6V49205APAG	9/6/2022	2/10/2023	8/10/2023	6V49205BPAGI
6V49205APAG8	9/6/2022	2/10/2023	8/10/2023	6V49205BPAGI8
6V49205APAGI	9/6/2022	2/10/2023	8/10/2023	6V49205BPAGI
6V49205APAGI8	9/6/2022	2/10/2023	8/10/2023	6V49205BPAGI8
6V49323ANLGI	9/6/2022	2/10/2023	8/10/2023	None
6V49323ANLGI8	9/6/2022	2/10/2023	8/10/2023	None
7005L20GB	9/6/2022	2/10/2023	8/10/2023	None
7005L25GB	9/6/2022	2/10/2023	8/10/2023	None
7005L35GB	9/6/2022	2/10/2023	8/10/2023	None
7005L55GB	9/6/2022	2/10/2023	8/10/2023	None
7005L70GB	9/6/2022	2/10/2023	8/10/2023	None
7005S25GB	9/6/2022	2/10/2023	8/10/2023	None
7005S35GB	9/6/2022	2/10/2023	8/10/2023	None
7005S55GB	9/6/2022	2/10/2023	8/10/2023	None
7005S70GB	9/6/2022	2/10/2023	8/10/2023	None
7006L15JG	9/6/2022	2/10/2023	8/10/2023	7006L15PFG
7006L15JG8	9/6/2022	2/10/2023	8/10/2023	7006L15PFG
7006L15PFG8	9/6/2022	2/10/2023	8/10/2023	7006L15PFG
7006L20FB	9/6/2022	2/10/2023	8/10/2023	None
7006L25FB	9/6/2022	2/10/2023	8/10/2023	None
7006L25GB	9/6/2022	2/10/2023	8/10/2023	None
7006L25PFG	9/6/2022	2/10/2023	8/10/2023	None
7006L25PFG8	9/6/2022	2/10/2023	8/10/2023	None
7006L35GB	9/6/2022	2/10/2023	8/10/2023	None
7006L55FB	9/6/2022	2/10/2023	8/10/2023	None
7006L55GB	9/6/2022	2/10/2023	8/10/2023	None
7006L70GB	9/6/2022	2/10/2023	8/10/2023	None
7006S25GB	9/6/2022	2/10/2023	8/10/2023	None
7006S35GB	9/6/2022	2/10/2023	8/10/2023	None
7006S35XLB	9/6/2022	2/10/2023	8/10/2023	None
7006S55GB	9/6/2022	2/10/2023	8/10/2023	None
7006S70GB	9/6/2022	2/10/2023	8/10/2023	None
7007L35GB	9/6/2022	2/10/2023	8/10/2023	None
7007S25GB	9/6/2022	2/10/2023	8/10/2023	None
7008L15PFG8	9/6/2022	2/10/2023	8/10/2023	7008L15PFG
7009L15PFG8	9/6/2022	2/10/2023	8/10/2023	7009L15PFG
7009L20PFG	9/6/2022	2/10/2023	8/10/2023	7009L15PFG
7009L20PFG8	9/6/2022	2/10/2023	8/10/2023	7009L20PFGI
7009L20PFGI8	9/6/2022	2/10/2023	8/10/2023	None
7014S12JG	9/6/2022	2/10/2023	8/10/2023	7014S12PFG
7014S12JG8	9/6/2022	2/10/2023	8/10/2023	7014S12PFG8
7024L15PFGI8	9/6/2022	2/10/2023	8/10/2023	7024L20PFGI
7024L20GB	9/6/2022	2/10/2023	8/10/2023	None
7024L25GB	9/6/2022	2/10/2023	8/10/2023	None
7024L35FB	9/6/2022	2/10/2023	8/10/2023	None
7024L35GB/2725	9/6/2022	2/10/2023	8/10/2023	None
7024L55GB	9/6/2022	2/10/2023	8/10/2023	None
7024L55GM	9/6/2022	2/10/2023	8/10/2023	None
7024L70GB	9/6/2022	2/10/2023	8/10/2023	None
7024S15PFG	9/6/2022	2/10/2023	8/10/2023	7024S15JG
7024S20GB	9/6/2022	2/10/2023	8/10/2023	None
7024S35FB	9/6/2022	2/10/2023	8/10/2023	None
7024S35GB	9/6/2022	2/10/2023	8/10/2023	None
7024S35PFG	9/6/2022	2/10/2023	8/10/2023	7024S15JG
7024S35PFG8	9/6/2022	2/10/2023	8/10/2023	7024S15JG
7024S45FB	9/6/2022	2/10/2023	8/10/2023	None
7024S55FB	9/6/2022	2/10/2023	8/10/2023	None
7024S70FB	9/6/2022	2/10/2023	8/10/2023	None
7024S70GB	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
7025L15JG8	9/6/2022	2/10/2023	8/10/2023	7025L15JG
7025L20FB	9/6/2022	2/10/2023	8/10/2023	None
7025L25FB	9/6/2022	2/10/2023	8/10/2023	None
7025L25GB	9/6/2022	2/10/2023	8/10/2023	None
7025L25GB/2725	9/6/2022	2/10/2023	8/10/2023	None
7025L35FB	9/6/2022	2/10/2023	8/10/2023	None
7025L45FB	9/6/2022	2/10/2023	8/10/2023	None
7025L55FB	9/6/2022	2/10/2023	8/10/2023	None
7025L55GB	9/6/2022	2/10/2023	8/10/2023	None
7025L70FB	9/6/2022	2/10/2023	8/10/2023	None
7025L70GB	9/6/2022	2/10/2023	8/10/2023	None
7025S25PFG	9/6/2022	2/10/2023	8/10/2023	7025L15JG
7025S25PFG8	9/6/2022	2/10/2023	8/10/2023	None
7025S35GB/2725	9/6/2022	2/10/2023	8/10/2023	None
7025S35PFGI8	9/6/2022	2/10/2023	8/10/2023	7025S35PFGI
7025S45FB	9/6/2022	2/10/2023	8/10/2023	None
7025S45GB/3215	9/6/2022	2/10/2023	8/10/2023	None
7025S55FB	9/6/2022	2/10/2023	8/10/2023	None
7025S55GB	9/6/2022	2/10/2023	8/10/2023	None
7025S70GB	9/6/2022	2/10/2023	8/10/2023	None
70261S25PFGI	9/6/2022	2/10/2023	8/10/2023	None
70261S25PFGI8	9/6/2022	2/10/2023	8/10/2023	None
7026L25GB	9/6/2022	2/10/2023	8/10/2023	None
7026L25GM	9/6/2022	2/10/2023	8/10/2023	None
7027L25G	9/6/2022	2/10/2023	8/10/2023	None
7038L15PFG	9/6/2022	2/10/2023	8/10/2023	None
7038L15PFG8	9/6/2022	2/10/2023	8/10/2023	None
7038L20PFGI	9/6/2022	2/10/2023	8/10/2023	None
7038L20PFGI8	9/6/2022	2/10/2023	8/10/2023	None
7052L20PFG	9/6/2022	2/10/2023	8/10/2023	None
7052L20PFG8	9/6/2022	2/10/2023	8/10/2023	None
7052L25PFGI	9/6/2022	2/10/2023	8/10/2023	None
7052L25PFGI8	9/6/2022	2/10/2023	8/10/2023	None
7052L30GB	9/6/2022	2/10/2023	8/10/2023	None
7052L35GB	9/6/2022	2/10/2023	8/10/2023	None
7052S20G	9/6/2022	2/10/2023	8/10/2023	None
7052S25G	9/6/2022	2/10/2023	8/10/2023	None
7052S30GB	9/6/2022	2/10/2023	8/10/2023	None
7052S35GB	9/6/2022	2/10/2023	8/10/2023	None
7054S25PRFG	9/6/2022	2/10/2023	8/10/2023	None
7054S25PRFG8	9/6/2022	2/10/2023	8/10/2023	None
709379L7PFG	9/6/2022	2/10/2023	8/10/2023	None
70V09L15PFG	9/6/2022	2/10/2023	8/10/2023	None
70V09L15PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V24L20JGI	9/6/2022	2/10/2023	8/10/2023	None
70V24L25PFG	9/6/2022	2/10/2023	8/10/2023	None
70V24L25PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V24S15PFG	9/6/2022	2/10/2023	8/10/2023	None
70V24S15PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V24S20PFG	9/6/2022	2/10/2023	8/10/2023	None
70V24S20PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V24S35PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V25S20PFG	9/6/2022	2/10/2023	8/10/2023	None
70V25S20PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V25S25PFG	9/6/2022	2/10/2023	8/10/2023	None
70V25S25PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V26L35G	9/6/2022	2/10/2023	8/10/2023	None
70V27L20PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V28L20PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V35L15PFG8	9/6/2022	2/10/2023	8/10/2023	None
70V37L20PFGI	9/6/2022	2/10/2023	8/10/2023	None
70V37L20PFGI8	9/6/2022	2/10/2023	8/10/2023	None
70V9089L12PFGI	9/6/2022	2/10/2023	8/10/2023	None
70V9089L12PFGI8	9/6/2022	2/10/2023	8/10/2023	None
70V9179L7PFG	9/6/2022	2/10/2023	8/10/2023	None
70V9199L9PFGI	9/6/2022	2/10/2023	8/10/2023	None
70V9199L9PFGI8	9/6/2022	2/10/2023	8/10/2023	None
70V9269L9PRFG	9/6/2022	2/10/2023	8/10/2023	None
70V9269L9PRFG8	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
70V9289L7PRFG	9/6/2022	2/10/2023	8/10/2023	None
70V9289L7PRFG8	9/6/2022	2/10/2023	8/10/2023	None
70V9289L9PRFGI	9/6/2022	2/10/2023	8/10/2023	None
70V9289L9PRFGI8	9/6/2022	2/10/2023	8/10/2023	None
70V9369L9PFG	9/6/2022	2/10/2023	8/10/2023	None
70V9369L9PFG8	9/6/2022	2/10/2023	8/10/2023	None
71024S20YG/2901	9/6/2022	2/10/2023	8/10/2023	71024S20TYG
71024S20YG8/2901	9/6/2022	2/10/2023	8/10/2023	71024S20TYG8
71256L120DB	9/6/2022	2/10/2023	8/10/2023	None
71256L150DB	9/6/2022	2/10/2023	8/10/2023	None
71256L85DB	9/6/2022	2/10/2023	8/10/2023	None
71256L85TDB	9/6/2022	2/10/2023	8/10/2023	None
71256S100TDB	9/6/2022	2/10/2023	8/10/2023	None
71256S25DB	9/6/2022	2/10/2023	8/10/2023	None
71256S35DB	9/6/2022	2/10/2023	8/10/2023	None
71256S35TDB	9/6/2022	2/10/2023	8/10/2023	None
71256S45DB	9/6/2022	2/10/2023	8/10/2023	None
71256S55TDB	9/6/2022	2/10/2023	8/10/2023	None
71256S85TDB	9/6/2022	2/10/2023	8/10/2023	None
7130LA25L48B	9/6/2022	2/10/2023	8/10/2023	None
7130LA35FB	9/6/2022	2/10/2023	8/10/2023	None
7130LA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7130LA55CB	9/6/2022	2/10/2023	8/10/2023	None
7130LA55FB	9/6/2022	2/10/2023	8/10/2023	None
7130LA55L48B	9/6/2022	2/10/2023	8/10/2023	None
7130SA100L48B	9/6/2022	2/10/2023	8/10/2023	None
7130SA25L48B	9/6/2022	2/10/2023	8/10/2023	None
7130SA35CB	9/6/2022	2/10/2023	8/10/2023	None
7130SA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7130SA45CB	9/6/2022	2/10/2023	8/10/2023	None
7130SA45FB	9/6/2022	2/10/2023	8/10/2023	None
7130SA55CB	9/6/2022	2/10/2023	8/10/2023	None
7132LA100L48B	9/6/2022	2/10/2023	8/10/2023	None
7132LA25L48B	9/6/2022	2/10/2023	8/10/2023	None
7132LA35FB	9/6/2022	2/10/2023	8/10/2023	None
7132LA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7132LA45FB	9/6/2022	2/10/2023	8/10/2023	None
7132LA55FB	9/6/2022	2/10/2023	8/10/2023	None
7132SA100L48B	9/6/2022	2/10/2023	8/10/2023	None
7132SA35CB	9/6/2022	2/10/2023	8/10/2023	None
7132SA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7133LA25GB	9/6/2022	2/10/2023	8/10/2023	None
7133LA55FB	9/6/2022	2/10/2023	8/10/2023	None
7133LA70GB	9/6/2022	2/10/2023	8/10/2023	None
7133LA90GB	9/6/2022	2/10/2023	8/10/2023	None
7133SA35FB	9/6/2022	2/10/2023	8/10/2023	None
7133SA35GB	9/6/2022	2/10/2023	8/10/2023	None
7133SA55FB	9/6/2022	2/10/2023	8/10/2023	None
7134LA35FB	9/6/2022	2/10/2023	8/10/2023	None
7134LA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7134LA45CB	9/6/2022	2/10/2023	8/10/2023	None
7134LA55CB	9/6/2022	2/10/2023	8/10/2023	None
7134LA55L48B	9/6/2022	2/10/2023	8/10/2023	None
7134LA70L48B	9/6/2022	2/10/2023	8/10/2023	None
7134SA25L48B	9/6/2022	2/10/2023	8/10/2023	None
7134SA35CB	9/6/2022	2/10/2023	8/10/2023	None
7134SA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7134SA45CB	9/6/2022	2/10/2023	8/10/2023	None
7134SA55CB	9/6/2022	2/10/2023	8/10/2023	None
7134SA55L48B	9/6/2022	2/10/2023	8/10/2023	None
7134SA70L48B	9/6/2022	2/10/2023	8/10/2023	None
7140LA100L48B	9/6/2022	2/10/2023	8/10/2023	None
7140LA35FB	9/6/2022	2/10/2023	8/10/2023	None
7140LA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7140LA55L48B	9/6/2022	2/10/2023	8/10/2023	None
7140SA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7140SA45FB	9/6/2022	2/10/2023	8/10/2023	None
7140SA55L48B	9/6/2022	2/10/2023	8/10/2023	None
7142LA100L48B	9/6/2022	2/10/2023	8/10/2023	None



Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
7142LA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7142LA55L48B	9/6/2022	2/10/2023	8/10/2023	None
7142SA100L48B	9/6/2022	2/10/2023	8/10/2023	None
7142SA35L48B	9/6/2022	2/10/2023	8/10/2023	None
7142SA55L48B	9/6/2022	2/10/2023	8/10/2023	None
7143LA25GB	9/6/2022	2/10/2023	8/10/2023	None
7143LA35FB	9/6/2022	2/10/2023	8/10/2023	None
7143LA35GB	9/6/2022	2/10/2023	8/10/2023	None
7143LA70GB	9/6/2022	2/10/2023	8/10/2023	None
7143LA90GB	9/6/2022	2/10/2023	8/10/2023	None
7143SA35FB	9/6/2022	2/10/2023	8/10/2023	None
7143SA35GB	9/6/2022	2/10/2023	8/10/2023	None
7143SA55GB	9/6/2022	2/10/2023	8/10/2023	None
7143SA70GB	9/6/2022	2/10/2023	8/10/2023	None
7143SA90GB	9/6/2022	2/10/2023	8/10/2023	None
7164L20DB	9/6/2022	2/10/2023	8/10/2023	None
7164L20TDB	9/6/2022	2/10/2023	8/10/2023	None
7164L25DB	9/6/2022	2/10/2023	8/10/2023	None
7164L55TDB	9/6/2022	2/10/2023	8/10/2023	None
7164L70TDB	9/6/2022	2/10/2023	8/10/2023	None
7164S20DB	9/6/2022	2/10/2023	8/10/2023	None
7164S20TDB	9/6/2022	2/10/2023	8/10/2023	None
7164S25DB	9/6/2022	2/10/2023	8/10/2023	None
7164S35TDB	9/6/2022	2/10/2023	8/10/2023	None
7164S45DB	9/6/2022	2/10/2023	8/10/2023	None
7164S70TDB	9/6/2022	2/10/2023	8/10/2023	None
7164S85TDB	9/6/2022	2/10/2023	8/10/2023	None
7200L20TDB	9/6/2022	2/10/2023	8/10/2023	None
7200L30TDB	9/6/2022	2/10/2023	8/10/2023	None
7201LA20DB	9/6/2022	2/10/2023	8/10/2023	None
7201LA20LB	9/6/2022	2/10/2023	8/10/2023	None
7201LA20LB8	9/6/2022	2/10/2023	8/10/2023	None
7201LA30DB	9/6/2022	2/10/2023	8/10/2023	None
7201LA30LB8	9/6/2022	2/10/2023	8/10/2023	None
7201LA30TDB	9/6/2022	2/10/2023	8/10/2023	None
7201LA50TDB	9/6/2022	2/10/2023	8/10/2023	None
7201LA80TDB	9/6/2022	2/10/2023	8/10/2023	None
7201SA30TDB	9/6/2022	2/10/2023	8/10/2023	None
7201SA50TDB	9/6/2022	2/10/2023	8/10/2023	None
7202LA20LB	9/6/2022	2/10/2023	8/10/2023	None
7202LA20LB8	9/6/2022	2/10/2023	8/10/2023	None
7202LA30LB	9/6/2022	2/10/2023	8/10/2023	None
7202LA30LB8	9/6/2022	2/10/2023	8/10/2023	None
7203L20DB	9/6/2022	2/10/2023	8/10/2023	None
7203L20LB	9/6/2022	2/10/2023	8/10/2023	None
7203L20LB8	9/6/2022	2/10/2023	8/10/2023	None
7203L20TDB	9/6/2022	2/10/2023	8/10/2023	None
7203L40DB	9/6/2022	2/10/2023	8/10/2023	None
7203L40LB	9/6/2022	2/10/2023	8/10/2023	None
7203L40LB8	9/6/2022	2/10/2023	8/10/2023	None
7204L20DB	9/6/2022	2/10/2023	8/10/2023	None
7204L20LB8	9/6/2022	2/10/2023	8/10/2023	None
7204L30LB8	9/6/2022	2/10/2023	8/10/2023	None
7204L50DB	9/6/2022	2/10/2023	8/10/2023	None
7205L20DB	9/6/2022	2/10/2023	8/10/2023	None
7205L20LB	9/6/2022	2/10/2023	8/10/2023	None
7205L20LB8	9/6/2022	2/10/2023	8/10/2023	None
7205L20TDB	9/6/2022	2/10/2023	8/10/2023	None
7205L30LB	9/6/2022	2/10/2023	8/10/2023	None
7205L30LB8	9/6/2022	2/10/2023	8/10/2023	None
7205L30TDB	9/6/2022	2/10/2023	8/10/2023	None
7206L20DB	9/6/2022	2/10/2023	8/10/2023	None
7206L20LB8	9/6/2022	2/10/2023	8/10/2023	None
7206L30DB	9/6/2022	2/10/2023	8/10/2023	None
7206L30LB	9/6/2022	2/10/2023	8/10/2023	None
7206L30LB8	9/6/2022	2/10/2023	8/10/2023	None
7207L20DB	9/6/2022	2/10/2023	8/10/2023	None
7207L20LB	9/6/2022	2/10/2023	8/10/2023	None
7207L20LB8	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
7207L30DB	9/6/2022	2/10/2023	8/10/2023	None
7207L30LB	9/6/2022	2/10/2023	8/10/2023	None
7207L30LB8	9/6/2022	2/10/2023	8/10/2023	None
72231L15PFGI	9/6/2022	2/10/2023	8/10/2023	None
72231L15PFGI8	9/6/2022	2/10/2023	8/10/2023	None
72241L10PFG	9/6/2022	2/10/2023	8/10/2023	None
72241L10PFG8	9/6/2022	2/10/2023	8/10/2023	None
723623L12PFG	9/6/2022	2/10/2023	8/10/2023	None
723623L12PFG8	9/6/2022	2/10/2023	8/10/2023	None
72801L15PFG	9/6/2022	2/10/2023	8/10/2023	None
72801L25PFG	9/6/2022	2/10/2023	8/10/2023	None
7282L12PAG5	9/6/2022	2/10/2023	8/10/2023	None
7282L15PAGI8	9/6/2022	2/10/2023	8/10/2023	None
7282L20PAG	9/6/2022	2/10/2023	8/10/2023	None
7282L20PAG8	9/6/2022	2/10/2023	8/10/2023	None
7285L15PAGI8	9/6/2022	2/10/2023	8/10/2023	None
72V201L15PFGI	9/6/2022	2/10/2023	8/10/2023	None
72V201L15PFGI8	9/6/2022	2/10/2023	8/10/2023	None
72V221L10PFG	9/6/2022	2/10/2023	8/10/2023	None
72V221L10PFG8	9/6/2022	2/10/2023	8/10/2023	None
72V221L15PFG	9/6/2022	2/10/2023	8/10/2023	None
72V221L15PFG8	9/6/2022	2/10/2023	8/10/2023	None
72V241L15PFG	9/6/2022	2/10/2023	8/10/2023	None
72V241L15PFG8	9/6/2022	2/10/2023	8/10/2023	None
72V251L10PFG	9/6/2022	2/10/2023	8/10/2023	None
72V251L10PFG8	9/6/2022	2/10/2023	8/10/2023	None
72V36100L7-5BB	9/6/2022	2/10/2023	8/10/2023	72V36100L6BCY
72V36100L7-5BB8	9/6/2022	2/10/2023	8/10/2023	72V36100L6BCY8
72V36100L7-5BBI	9/6/2022	2/10/2023	8/10/2023	72V36100L6BCY
72V36100L7-5BBI8	9/6/2022	2/10/2023	8/10/2023	72V36100L6BCY8
72V3640L7-5BB	9/6/2022	2/10/2023	8/10/2023	None
72V3640L7-5BB8	9/6/2022	2/10/2023	8/10/2023	None
72V3650L7-5BB	9/6/2022	2/10/2023	8/10/2023	None
72V3650L7-5BB8	9/6/2022	2/10/2023	8/10/2023	None
72V3650L7-5BBI	9/6/2022	2/10/2023	8/10/2023	None
72V3650L7-5BBI8	9/6/2022	2/10/2023	8/10/2023	None
72V3660L6BB	9/6/2022	2/10/2023	8/10/2023	None
72V3660L6BB8	9/6/2022	2/10/2023	8/10/2023	None
72V3660L7-5BB	9/6/2022	2/10/2023	8/10/2023	None
72V3660L7-5BB8	9/6/2022	2/10/2023	8/10/2023	None
72V3660L7-5BBI	9/6/2022	2/10/2023	8/10/2023	None
72V3660L7-5BBI8	9/6/2022	2/10/2023	8/10/2023	None
72V3670L7-5BB	9/6/2022	2/10/2023	8/10/2023	None
72V3670L7-5BB8	9/6/2022	2/10/2023	8/10/2023	None
72V3680L7-5BB	9/6/2022	2/10/2023	8/10/2023	None
72V3680L7-5BB8	9/6/2022	2/10/2023	8/10/2023	None
72V3690L7-5BB	9/6/2022	2/10/2023	8/10/2023	None
72V3690L7-5BB8	9/6/2022	2/10/2023	8/10/2023	None
72V3690L7-5BBI	9/6/2022	2/10/2023	8/10/2023	None
72V3690L7-5BBI8	9/6/2022	2/10/2023	8/10/2023	None
72V71650BB	9/6/2022	2/10/2023	8/10/2023	None
72V81L15PAG	9/6/2022	2/10/2023	8/10/2023	None
72V81L15PAG8	9/6/2022	2/10/2023	8/10/2023	None
72V831L10PFG	9/6/2022	2/10/2023	8/10/2023	None
72V831L10PFG8	9/6/2022	2/10/2023	8/10/2023	None
72V85L15PAG	9/6/2022	2/10/2023	8/10/2023	None
72V85L15PAG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT162245CTPAG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT162245CTPVG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT162373ATPAG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT162373CTPAG	9/6/2022	2/10/2023	8/10/2023	None
74FCT162373CTPAG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT162373CTPVG	9/6/2022	2/10/2023	8/10/2023	None
74FCT162373ETPAG	9/6/2022	2/10/2023	8/10/2023	None
74FCT162373ETPAG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT162373ETPVG	9/6/2022	2/10/2023	8/10/2023	None
74FCT162373ETPVG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT16244CTPAG	9/6/2022	2/10/2023	8/10/2023	None
74FCT16244CTPVG8	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
74FCT16245ATEB	9/6/2022	2/10/2023	8/10/2023	None
74FCT16245CTEB	9/6/2022	2/10/2023	8/10/2023	None
74FCT16245TEB	9/6/2022	2/10/2023	8/10/2023	None
74FCT163245APVG	9/6/2022	2/10/2023	8/10/2023	None
74FCT16373ATPVG	9/6/2022	2/10/2023	8/10/2023	None
74FCT2245ATQG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT2245CTQG	9/6/2022	2/10/2023	8/10/2023	None
74FCT2245CTQG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT244ATLB	9/6/2022	2/10/2023	8/10/2023	None
74FCT244CTLB	9/6/2022	2/10/2023	8/10/2023	None
74FCT244CTPGG	9/6/2022	2/10/2023	8/10/2023	None
74FCT244CTPGG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT244CTPYG	9/6/2022	2/10/2023	8/10/2023	None
74FCT244CTPYG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT244TLB	9/6/2022	2/10/2023	8/10/2023	None
74FCT245ATDB	9/6/2022	2/10/2023	8/10/2023	None
74FCT245ATPGG	9/6/2022	2/10/2023	8/10/2023	None
74FCT245ATPGG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT245ATPYG	9/6/2022	2/10/2023	8/10/2023	None
74FCT245ATPYG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT245CTDB	9/6/2022	2/10/2023	8/10/2023	None
74FCT245CTLB	9/6/2022	2/10/2023	8/10/2023	None
74FCT245TDB	9/6/2022	2/10/2023	8/10/2023	None
74FCT3244PGG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT3245AQG	9/6/2022	2/10/2023	8/10/2023	None
74FCT3245QG	9/6/2022	2/10/2023	8/10/2023	None
74FCT3245QG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT374ATDB	9/6/2022	2/10/2023	8/10/2023	None
74FCT374ATLB	9/6/2022	2/10/2023	8/10/2023	None
74FCT374CTDB	9/6/2022	2/10/2023	8/10/2023	None
74FCT374CTLB	9/6/2022	2/10/2023	8/10/2023	None
74FCT374TDB	9/6/2022	2/10/2023	8/10/2023	None
74FCT374TLB	9/6/2022	2/10/2023	8/10/2023	None
74FCT573ATQG	9/6/2022	2/10/2023	8/10/2023	None
74FCT573ATQG8	9/6/2022	2/10/2023	8/10/2023	None
74FCT573CTQG	9/6/2022	2/10/2023	8/10/2023	None
74FCT573CTQG8	9/6/2022	2/10/2023	8/10/2023	None
74LVC16827APAG	9/6/2022	2/10/2023	8/10/2023	None
74LVC16827APAG8	9/6/2022	2/10/2023	8/10/2023	None
810N322BKI-02LF	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI
810N322BKI-02LFT	9/6/2022	2/10/2023	8/10/2023	5L35023B-000NLGI8
814S208BKILF	9/6/2022	2/10/2023	8/10/2023	RC21008A000GND#BBO
814S208BKILFT	9/6/2022	2/10/2023	8/10/2023	RC21008A000GND#KBO
8403608JA	9/6/2022	2/10/2023	8/10/2023	None
8403608LA	9/6/2022	2/10/2023	8/10/2023	None
8403609LA	9/6/2022	2/10/2023	8/10/2023	None
8403610JA	9/6/2022	2/10/2023	8/10/2023	None
8403610LA	9/6/2022	2/10/2023	8/10/2023	None
8403611JA	9/6/2022	2/10/2023	8/10/2023	None
8403611LA	9/6/2022	2/10/2023	8/10/2023	None
8403612JA	9/6/2022	2/10/2023	8/10/2023	None
8403612LA	9/6/2022	2/10/2023	8/10/2023	None
8403613JA	9/6/2022	2/10/2023	8/10/2023	None
8403613LA	9/6/2022	2/10/2023	8/10/2023	None
841N4830AKI-09LF	9/6/2022	2/10/2023	8/10/2023	9FGV1005C000LTGI
841N4830AKI-09LFT	9/6/2022	2/10/2023	8/10/2023	9FGV1005C000LTGI8
841N4830AKILF	9/6/2022	2/10/2023	8/10/2023	9FGV1005C000LTGI
841N4830AKILFT	9/6/2022	2/10/2023	8/10/2023	9FGV1005C000LTGI8
841S012DKILF	9/6/2022	2/10/2023	8/10/2023	RC21008A000GND#BBO
841S012DKILFT	9/6/2022	2/10/2023	8/10/2023	RC21008A000GND#KBO
8430S07AKILF	9/6/2022	2/10/2023	8/10/2023	None
8430S07AKILFT	9/6/2022	2/10/2023	8/10/2023	None
8430S10BYI-02LF	9/6/2022	2/10/2023	8/10/2023	None
8430S10BYI-02LFT	9/6/2022	2/10/2023	8/10/2023	None
843N571AKILF	9/6/2022	2/10/2023	8/10/2023	843N571BKILF
843N571AKILFT	9/6/2022	2/10/2023	8/10/2023	843N571BKILFT
843S104BKI-133LF	9/6/2022	2/10/2023	8/10/2023	None
843S104BKI-133LFT	9/6/2022	2/10/2023	8/10/2023	None
843S304BKI-100LF	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
843S304BK1-100LFT	9/6/2022	2/10/2023	8/10/2023	None
844N236AKILF	9/6/2022	2/10/2023	8/10/2023	None
844N236AKILFT	9/6/2022	2/10/2023	8/10/2023	None
849S625BYILF	9/6/2022	2/10/2023	8/10/2023	RC21008A000GND#BBO
849S625BYILFT	9/6/2022	2/10/2023	8/10/2023	RC21008A000GND#KBO
850S1201BGILF	9/6/2022	2/10/2023	8/10/2023	None
850S1201BGILFT	9/6/2022	2/10/2023	8/10/2023	None
851S201CKILF	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#BBO
851S201CKILFT	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#KBO
853S011CGILF	9/6/2022	2/10/2023	8/10/2023	8SLVP1102ANLGI
853S011CGILFT	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI8
853S011CMILF	9/6/2022	2/10/2023	8/10/2023	8SLVP1102ANLGI
853S011CMILFT	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI8
853S031BYILF	9/6/2022	2/10/2023	8/10/2023	8SLVP1208ANBGI
853S031BYILFT	9/6/2022	2/10/2023	8/10/2023	8SLVP1208ANBGI8
853S12AKILF	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI
853S12AKILFT	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI8
853S9252BKILF	9/6/2022	2/10/2023	8/10/2023	8SLVP1102ANLGI
853S9252BKILF/W	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI/W
853S9252BKILFT	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI8
854S006AGILF	9/6/2022	2/10/2023	8/10/2023	None
854S006AGILFT	9/6/2022	2/10/2023	8/10/2023	None
858S011AKILF	9/6/2022	2/10/2023	8/10/2023	8SLVP1102ANLGI
858S011AKILFT	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI8
8NOQV01EH-0009CD	9/6/2022	2/10/2023	8/10/2023	XFN336148.500000I
8NOQV01EH-0009CD8	9/6/2022	2/10/2023	8/10/2023	XFN336148.500000I
8NOQV01EH-0009CDI	9/6/2022	2/10/2023	8/10/2023	XFN336148.500000I
8NOQV01EH-0009CDI8	9/6/2022	2/10/2023	8/10/2023	XFN336148.500000I
8NOQV01EH-0110CDI	9/6/2022	2/10/2023	8/10/2023	XFN336100.000000I
8NOQV01EH-0110CDI8	9/6/2022	2/10/2023	8/10/2023	XFN336100.000000I
8NOQV01KH-0108CDI	9/6/2022	2/10/2023	8/10/2023	XFN336156.250000I
8NOQV01KH-0108CDI8	9/6/2022	2/10/2023	8/10/2023	XFN336156.250000I
8NOQV01KH-0208CDI	9/6/2022	2/10/2023	8/10/2023	XFN336625.000000I
8NOQV01KH-0208CDI8	9/6/2022	2/10/2023	8/10/2023	XFN336625.000000I
8NOQV01LH-0108CDI	9/6/2022	2/10/2023	8/10/2023	XFN336156.250000I
8NOQV01LH-0108CDI8	9/6/2022	2/10/2023	8/10/2023	XFN336156.250000I
8S89874BKILF	9/6/2022	2/10/2023	8/10/2023	8SLVP1102ANLGI
8S89874BKILF/W	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI/W
8S89874BKILFT	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI8
8T349316NLGI	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI
8T349316NLGI8	9/6/2022	2/10/2023	8/10/2023	8SLVD1212ANLGI8
8T49N1012-001NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-001NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-002NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-002NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-003NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-003NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-004NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-004NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-005NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-005NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-006NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-006NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-007NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-007NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-008NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-008NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-010NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-010NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-012NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-012NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-100NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-100NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-101NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-101NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-102NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-102NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-103NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-103NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
8T49N1012-991NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-991NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-992NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-992NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-993NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-993NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-994NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-994NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012-998NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012-998NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N1012NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI
8T49N1012NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS0412NLGI8
8T49N205A-001NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-001NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-002NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-002NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-004NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-004NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-005NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-005NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-006NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-006NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-007NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-007NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-009NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-009NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-011NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-011NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-012NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-012NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-013NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-013NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N205A-014NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-999NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N205A-999NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N222B-000NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N222B-000NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N222B-004NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N222B-004NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N222B-108NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N222B-108NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N222B-109NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N222B-109NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N222B-110NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N222B-110NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N222B-123NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N222B-123NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N222B-127NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N222B-127NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N222B-129NLGI	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#BB0
8T49N222B-129NLGI8	9/6/2022	2/10/2023	8/10/2023	RC22504A000G NK#KB0
8T49N445-999ASGI	9/6/2022	2/10/2023	8/10/2023	RC32012A000G N2#BB0
8T49N445-999ASGI8	9/6/2022	2/10/2023	8/10/2023	RC32012A000G N2#KB0
8T49N4811NLGI	9/6/2022	2/10/2023	8/10/2023	8V49NS4812NLGI
8T49N4811NLGI/W	9/6/2022	2/10/2023	8/10/2023	8V49NS4812NLGI8
8T49N4811NLGI8	9/6/2022	2/10/2023	8/10/2023	8V49NS4812NLGI8
8T49N488A-000ASGI	9/6/2022	2/10/2023	8/10/2023	RC31008A000G ND#BB0
8T49N488A-000ASGI8	9/6/2022	2/10/2023	8/10/2023	RC31008A000G ND#KB0
8T49N488A-999ASGI	9/6/2022	2/10/2023	8/10/2023	RC31008A000G ND#BB0
8T49N488A-999ASGI8	9/6/2022	2/10/2023	8/10/2023	RC31008A000G ND#KB0
8T49N488AASGI	9/6/2022	2/10/2023	8/10/2023	RC31008A000G ND#BB0
8T49N488AASGI8	9/6/2022	2/10/2023	8/10/2023	RC31008A000G ND#KB0
8T53S111NLGI	9/6/2022	2/10/2023	8/10/2023	None
8T53S111NLGI8	9/6/2022	2/10/2023	8/10/2023	None
8T73S208BNLGI	9/6/2022	2/10/2023	8/10/2023	8T73S208B-01NLGI
8T73S208BNLGI8	9/6/2022	2/10/2023	8/10/2023	8T73S208B-01NLGI8
8V19N880BDGI	9/6/2022	2/10/2023	8/10/2023	8V19N882NVGI
8V19N880BDGI8	9/6/2022	2/10/2023	8/10/2023	8V19N882NVGI8
8V41N004NLGI	9/6/2022	2/10/2023	8/10/2023	9FGV1001C000NBGI

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
8V41N004NLG18	9/6/2022	2/10/2023	8/10/2023	9FGV1001C000NBG18
8V41N354NLG	9/6/2022	2/10/2023	8/10/2023	None
8V41N354NLG8	9/6/2022	2/10/2023	8/10/2023	None
8V44N4614NLGI	9/6/2022	2/10/2023	8/10/2023	RC31008A000GND#BBO
8V44N4614NLGI/W	9/6/2022	2/10/2023	8/10/2023	RC31008A000GND#KBO
8V44N4614NLG18	9/6/2022	2/10/2023	8/10/2023	RC31008A000GND#KBO
8V54816ANLG	9/6/2022	2/10/2023	8/10/2023	None
8V54816ANLG8	9/6/2022	2/10/2023	8/10/2023	None
8V54816ANLGI	9/6/2022	2/10/2023	8/10/2023	None
8V54816ANLGI8	9/6/2022	2/10/2023	8/10/2023	None
8V74S4622NLGI	9/6/2022	2/10/2023	8/10/2023	8P34S1102NLGI
8V74S4622NLGI/W	9/6/2022	2/10/2023	8/10/2023	8P34S1102NLGI8
8V74S4622NLG18	9/6/2022	2/10/2023	8/10/2023	8P34S1102NLG18
8V89313NLG	9/6/2022	2/10/2023	8/10/2023	8A34002E-000NLG
8V89313NLG8	9/6/2022	2/10/2023	8/10/2023	8A34002E-000NLG8
8V89704ANLGI	9/6/2022	2/10/2023	8/10/2023	9FGV1001C000NBGI
8V89704ANLGI8	9/6/2022	2/10/2023	8/10/2023	9FGV1001C000NBG18
8V97053NLGI	9/6/2022	2/10/2023	8/10/2023	8V97051LNLGI
8V97053NLGI/W	9/6/2022	2/10/2023	8/10/2023	8V97051LNLGI/W
8V97053NLG18	9/6/2022	2/10/2023	8/10/2023	8V97051LNLG18
932SQL435AKLF	9/6/2022	2/10/2023	8/10/2023	None
932SQL435AKLFT	9/6/2022	2/10/2023	8/10/2023	None
932SQL436AKLF	9/6/2022	2/10/2023	8/10/2023	None
932SQL436AKLFT	9/6/2022	2/10/2023	8/10/2023	None
932SQL450BKLF	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLF
932SQL450BKLF/W	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLFT
932SQL450BKLFT	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLFT
932SQL456AGILF	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLF
932SQL456AGILFT	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLFT
932SQL456AGLFT	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLF
932SQL456AKILF	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLF
932SQL456AKILFT	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLFT
932SQL456AKLFT	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLF
932SQL456AKLFT	9/6/2022	2/10/2023	8/10/2023	932SQ420DGLFT
9DBU0731AKILF	9/6/2022	2/10/2023	8/10/2023	RC19008AGND#BBO
9DBU0731AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19008AGND#KBO
9DBU0741AKILF	9/6/2022	2/10/2023	8/10/2023	RC19008A100GND#BBO
9DBU0741AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19008A100GND#KBO
9DBU0741AKLF	9/6/2022	2/10/2023	8/10/2023	RC19008A100GND#BBO
9DBU0741AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19008A100GND#KBO
9DBU0931AKILF	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#BBO
9DBU0931AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#KBO
9DBU0931AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#BBO
9DBU0931AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#KBO
9DBU0941AKILF	9/6/2022	2/10/2023	8/10/2023	RC19013A100GNG#BBO
9DBU0941AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19013A100GNG#KBO
9DBU0941AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013A100GNG#BBO
9DBU0941AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013A100GNG#KBO
9DBV0731AKILF	9/6/2022	2/10/2023	8/10/2023	RC19008AGND#BBO
9DBV0731AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19008AGND#KBO
9DBV0731AKLF	9/6/2022	2/10/2023	8/10/2023	RC19008AGND#BBO
9DBV0731AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19008AGND#KBO
9DBV0741AKILF	9/6/2022	2/10/2023	8/10/2023	RC19008A100GND#BBO
9DBV0741AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19008A100GND#KBO
9DBV0741AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19008A100GND#BBO
9DBV0741AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19008A100GND#KBO
9DBV0931AKILF	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#BBO
9DBV0931AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#KBO
9DBV0931AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#BBO
9DBV0931AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#KBO
9DBV0941AKILF	9/6/2022	2/10/2023	8/10/2023	RC19013A100GNG#BBO
9DBV0941AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19013A100GNG#KBO
9DBV0941AKLF	9/6/2022	2/10/2023	8/10/2023	RC19013A100GNG#BBO
9DBV0941AKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013A100GNG#KBO
9DMU0131AKILF	9/6/2022	2/10/2023	8/10/2023	9DMV0131BKILF
9DMU0131AKILFT	9/6/2022	2/10/2023	8/10/2023	9DMV0131BKILFT
9DMU0431AKILF	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#BBO
9DMU0431AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#KBO

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
9DMU0441AKILF	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#BBO
9DMU0441AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#KBO
9DMV0431AKILF	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#BBO
9DMV0431AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#KBO
9DMV0441AKILF	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#BBO
9DMV0441AKILFT	9/6/2022	2/10/2023	8/10/2023	RC19204AGNL#KBO
9FGL1214AKLF	9/6/2022	2/10/2023	8/10/2023	RC21012A000GNA#BBO
9FGL1214AKLFT	9/6/2022	2/10/2023	8/10/2023	RC21012A000GNA#KBO
9FGL1216AGLF	9/6/2022	2/10/2023	8/10/2023	RC21012A000GNA#BBO
9FGL1216AGLFT	9/6/2022	2/10/2023	8/10/2023	RC21012A000GNA#KBO
9FGL1220AKLF	9/6/2022	2/10/2023	8/10/2023	RC21012A000GNA#BBO
9FGL1220AKLFT	9/6/2022	2/10/2023	8/10/2023	RC21012A000GNA#KBO
9FGL699AKLF	9/6/2022	2/10/2023	8/10/2023	9FGL0651CKILF
9FGL699AKLFT	9/6/2022	2/10/2023	8/10/2023	9FGL0651CKILFT
9FGU0631CKILF	9/6/2022	2/10/2023	8/10/2023	9FGU0641AKILF
9FGU0631CKILFT	9/6/2022	2/10/2023	8/10/2023	9FGU0641AKILFT
9FGU0631CKLF	9/6/2022	2/10/2023	8/10/2023	9FGU0641AKILF
9FGU0631CKLFT	9/6/2022	2/10/2023	8/10/2023	9FGU0641AKILFT
9FGU0831CKILF	9/6/2022	2/10/2023	8/10/2023	9FGU0841AKILF
9FGU0831CKILFT	9/6/2022	2/10/2023	8/10/2023	9FGU0841AKILFT
9FGU0831CKLF	9/6/2022	2/10/2023	8/10/2023	9FGU0841AKILF
9FGU0831CKLFT	9/6/2022	2/10/2023	8/10/2023	9FGU0841AKILFT
9FGV0631CKILF	9/6/2022	2/10/2023	8/10/2023	9FGV0641AKILF
9FGV0631CKILFT	9/6/2022	2/10/2023	8/10/2023	9FGV0641AKILFT
9FGV0631CKLF	9/6/2022	2/10/2023	8/10/2023	9FGV0641AKILF
9FGV0631CKLFT	9/6/2022	2/10/2023	8/10/2023	9FGV0641AKILFT
9FGV0831CKILF	9/6/2022	2/10/2023	8/10/2023	9FGV0841AKILF
9FGV0831CKILFT	9/6/2022	2/10/2023	8/10/2023	9FGV0841AKILFT
9FGV0831CKLF	9/6/2022	2/10/2023	8/10/2023	9FGV0841AKILF
9FGV0831CKLFT	9/6/2022	2/10/2023	8/10/2023	9FGV0841AKILFT
9LPRS477DKLF	9/6/2022	2/10/2023	8/10/2023	None
9LPRS477DKLFT	9/6/2022	2/10/2023	8/10/2023	None
9LRS3187BKILF	9/6/2022	2/10/2023	8/10/2023	None
9LRS3187BKILF-INT	9/6/2022	2/10/2023	8/10/2023	None
9LRS3187BKILFT	9/6/2022	2/10/2023	8/10/2023	None
9LRS3187BKILFT-INT	9/6/2022	2/10/2023	8/10/2023	None
9LRS3187BKLF	9/6/2022	2/10/2023	8/10/2023	None
9LRS3187BKLFT	9/6/2022	2/10/2023	8/10/2023	None
9VRS4338DKILF	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLF
9VRS4338DKILFT	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLFT
9VRS4338DKLF	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLF
9VRS4338DKLF-INT	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLF
9VRS4338DKLFT	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLFT
9VRS4338DKLFT-INT	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLFT
9VRS4420BKLF	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLF
9VRS4420BKLF-INO	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLF
9VRS4420BKLFT	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLFT
9VRS4420BKLFT-INO	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLFT
9VRS4451AKILF	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLF
9VRS4451AKILFT	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLFT
9VRS4451AKLF	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLF
9VRS4451AKLFT	9/6/2022	2/10/2023	8/10/2023	9VRS4420DKLFT
9ZML1232BKLF	9/6/2022	2/10/2023	8/10/2023	9ZML1232EKILF
9ZML1232BKLFT	9/6/2022	2/10/2023	8/10/2023	9ZML1232EKILFT
9ZX21201BKLF	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#BBO
9ZX21201BKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#KBO
9ZX21207BKLF	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#BBO
9ZX21207BKLFT	9/6/2022	2/10/2023	8/10/2023	RC19013AGNG#KBO
CA91L862A-50ILV	9/6/2022	2/10/2023	8/10/2023	None
CA91L862A-50ILV	9/6/2022	2/10/2023	8/10/2023	None
GX62474-HIU	9/6/2022	2/10/2023	8/10/2023	None
GX62476-HIU	9/6/2022	2/10/2023	8/10/2023	None
MK5811CMLF	9/6/2022	2/10/2023	8/10/2023	5P49V6975A000LTGI
MK5811CMLFT	9/6/2022	2/10/2023	8/10/2023	5P49V6975A000LTGI8
P9025AC-R1NBGI	9/6/2022	2/10/2023	8/10/2023	None
P9025AC-R1NBGI8	9/6/2022	2/10/2023	8/10/2023	None
P9025AC-R-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9025AC-R-EVKSMP	9/6/2022	2/10/2023	8/10/2023	None
P9025AC-RNBGI	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
P9025AC-RNBGI8	9/6/2022	2/10/2023	8/10/2023	None
P9027LP-RAWGI	9/6/2022	2/10/2023	8/10/2023	None
P9027LP-RAWGI8	9/6/2022	2/10/2023	8/10/2023	None
P9027LP-R-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9221-20AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-20AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9221-23AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-23AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9221-24AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-24AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9221-P1AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-P1AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9221-PAHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-PAHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9221-P-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9221-R11AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-R11AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9221-R1AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-R1AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9221-R6AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-R6AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9221-R7AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9221-R7AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9222-R2AZGI	9/6/2022	2/10/2023	8/10/2023	P9222-RAZGI
P9222-R2AZGI8	9/6/2022	2/10/2023	8/10/2023	P9222-RAZGI8
P9222-R3AZGI	9/6/2022	2/10/2023	8/10/2023	P9222-RAZGI
P9222-R3AZGI8	9/6/2022	2/10/2023	8/10/2023	P9222-RAZGI8
P9222-R6AZGI	9/6/2022	2/10/2023	8/10/2023	P9222-RAZGI
P9222-R6AZGI8	9/6/2022	2/10/2023	8/10/2023	P9222-RAZGI8
P9225-5AHGI	9/6/2022	2/10/2023	8/10/2023	P9225-RAHGI
P9225-5AHGI8	9/6/2022	2/10/2023	8/10/2023	P9225-RAHGI8
P9235-0NDGI	9/6/2022	2/10/2023	8/10/2023	None
P9235-0NDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9235-17NDGI	9/6/2022	2/10/2023	8/10/2023	None
P9235-17NDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9235A-0NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-0NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-10NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-10NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-16NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-16NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-18NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-18NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-8NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-8NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-B0NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-B0NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-B1NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-B1NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9235A-R2NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-R2NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-R5NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-R5NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-R6NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-R6NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-R7NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-R7NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-RNDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9235A-RNDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9235A-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9236A-0NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9236A-0NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9236A-B1NDGI	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI
P9236A-B1NDGI8	9/6/2022	2/10/2023	8/10/2023	P9235A-RBNDGI8
P9236A-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9237-0NDGI	9/6/2022	2/10/2023	8/10/2023	None
P9237-0NDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9237-10NDGI	9/6/2022	2/10/2023	8/10/2023	None



Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
P9237-10NDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9237-8NDGI	9/6/2022	2/10/2023	8/10/2023	None
P9237-8NDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9237-9NDGI	9/6/2022	2/10/2023	8/10/2023	None
P9237-9NDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9237-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9237-RBNDGI	9/6/2022	2/10/2023	8/10/2023	None
P9237-RBNDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9241-G0NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9241-G0NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9241-G1NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9241-G1NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9241-GB1NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9241-GB1NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9241-GBNDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9241-GBNDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9241-G-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9241-G-EVKSMP	9/6/2022	2/10/2023	8/10/2023	None
P9241-GNDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9241-GNDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G0NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G0NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G1NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G1NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G2NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G2NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G3NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G3NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G4NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G4NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G5NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G5NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G6NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G6NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G7NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G7NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G8NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G8NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G9NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-G9NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-G-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9242-G-EVKSMP	9/6/2022	2/10/2023	8/10/2023	None
P9242-GNDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-GNDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-P-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9242-PNDGI	9/6/2022	2/10/2023	8/10/2023	None
P9242-PNDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9242-R0NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-R0NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-R10NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-R10NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-R4NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-R4NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-R6NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-R6NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-R8NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9242-R8NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9242-R-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9242-R-EVKSMP	9/6/2022	2/10/2023	8/10/2023	None
P9243-G1NDGI	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI
P9243-G1NDGI8	9/6/2022	2/10/2023	8/10/2023	P9243-GBNDGI8
P9245-0NDGI	9/6/2022	2/10/2023	8/10/2023	None
P9245-0NDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9245-R2C-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9245-R2CNDGI	9/6/2022	2/10/2023	8/10/2023	None
P9245-R2CNDGI8	9/6/2022	2/10/2023	8/10/2023	None
P9245-R3C-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9245-R3CNDGI	9/6/2022	2/10/2023	8/10/2023	None
P9245-R3CNDGI8	9/6/2022	2/10/2023	8/10/2023	None

Exact Renesas Part # No other variation is being impacted.	Notice Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement/Similar / Re-Design
P9247-1NDGI	9/6/2022	2/10/2023	8/10/2023	P9247-RBNDGI
P9247-1NDGI8	9/6/2022	2/10/2023	8/10/2023	P9247-RBNDGI8
P9247-2NDGI	9/6/2022	2/10/2023	8/10/2023	P9247-RBNDGI
P9247-2NDGI8	9/6/2022	2/10/2023	8/10/2023	P9247-RBNDGI8
P9320-0AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9320-0AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9320S-0AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9320S-0AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9320S-1AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9320S-1AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9320S-2AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9320S-2AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9323S-0AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9323S-0AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9323S-1AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9323S-1AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9382A-0AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9382A-0AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9382A-5AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9382A-5AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9382A-6AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9382A-6AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9382A-9AHGI	9/6/2022	2/10/2023	8/10/2023	None
P9382A-9AHGI8	9/6/2022	2/10/2023	8/10/2023	None
P9382A-EVK	9/6/2022	2/10/2023	8/10/2023	None
P9415-10AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-10AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-11AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-11AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-12AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-12AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-13AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-13AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-1AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-1AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-5AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-5AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-6AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-6AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-8AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-8AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-9AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-9AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9415-R4AWQI	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI
P9415-R4AWQI8	9/6/2022	2/10/2023	8/10/2023	P9415-RAWQI8
P9418-1AWQI	9/6/2022	2/10/2023	8/10/2023	P9418-0AWQI
P9418-1AWQI8	9/6/2022	2/10/2023	8/10/2023	P9418-0AWQI8