

1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type				
02	006	016	0000001515	See list below	Connectors	CD	
02	006	016	0000001516	See list below	Connectors	CG	
02	006	016	0000001542	See list below	Connectors	FKG	
02	006	016	0000001538	See list below	Connectors	FKH	
02	006	016	0000001540	See list below	Connectors	FKHD	
02	006	016	0000001539	See list below	Connectors	FKI	
02	006	016	0000001541	See list below	Connectors	FKID	
02	005	016	0000001113	See list below	Connectors	KD	
02	005	016	0000001111	See list below	Connectors	KEB2	
02	006	016	0000001513	See list below	Connectors	KFB2	
02	005	016	0000001114	See list below	Connectors	KG	
02	005	116	0000001134	See list below	Connectors	KP01	
02	005	016	0000001210	See list below	Connectors	6762	
02	005	016	0000001209	See list below	Connectors	6765	

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

See detailed List of Part numbers at the end of the document

2 Type of change

- Change of production process
- 2nd source for built-in line switch to secure availability and delivery to customers.

3 Detailed description of change



- Change: 2nd source for the built-in line switch
The built-in line switch can be delivered by 2 different suppliers from now on (switches are technically identical according SCHURTER Specifications)

4 Reason of change

- Production process improvement
Identical built-in line switch integration successfully accomplished to overcome difficulties in supply.

2nd Source built-in line switch Approval Files:

- ENEC File Number ENEC-04166
- UL File Number E524325

Product Change Notification					PCN CD/CG/FKG/FKH/FKHD/FKI/FKID/KD/KEB2/K		D10-064-256
owner	creation date	release date	released by	change order	rev	page	
kummerpa	30.03.2022	20.09.2022	muehlema	2024756	A	1 of 4	

5 Release date

The change will be rolled-out starting ww 01/2023 (Date code 2301 or higher on label).

6 Impact of change and recommended action

- Form
- Fit
- Function
- Manufacturing Note: 2nd source for built-in line switch with updated approvals
- Label
- Packaging

7 Reference Documents / Attachments

Kind of document	Document Title
Data Sheet	Type CD
Data Sheet	Type CG
-	Type FKG
Data Sheet	Type FKH
Data Sheet	Type FKHD
Data Sheet	Type FKI
Data Sheet	Type FKID
Data Sheet	Type KD
Data Sheet	Type KEB2
Data Sheet	Type KFB2
Data Sheet	Type KG
Data Sheet	Type KP01
Data Sheet	Type 6762
Data Sheet	Type 6765

List of part numbers affected for type CD				
CD11.1501.151	CD24.1133.151	CD34.4133.151	CD64.4101.151	CDE4.1101.151
CD11.4501.151	CD24.4101.151	CD41.1501.151	CDA1.4501.151	CDE4.4101.151
CD14.1101.151	CD24.4101.151.01	CD41.4501.151	CDA4.1101.151	CDE4.4133.151
CD14.1133.151	CD24.4133.151	CD43.1101.151	CDA4.4101.151	CDG4.4101.151
CD14.4101.151	CD31.1501.151	CD44.1101.151	CDB4.4101.151	CDG4.4133.151
CD21.1501.151	CD31.4501.151	CD44.1101.151.01	CDC4.1101.151	CDH4.1101.151
CD21.4501.151	CD34.1101.151	CD44.4101.151	CDC4.4101.151	CDL4.1101.151
CD23.4101.151	CD34.1133.151	CD61.1501.151	CDC4.4101.151.01	CDL4.4101.151
CD23.4101.198	CD34.4101.151	CD61.4501.151	CDC4.4133.151	CDL4.4133.151
CD24.1101.151	CD34.4132.151	CD64.1101.151	CDD4.4101.151	CDM4.4101.151

List of part numbers affected for type CG				
CG10.6101.151	CG30.6101.151	CG60.6101.151	CGD6.5101.151	CGG0.6101.151
CG16.5101.151	CG36.5101.151	CG66.5101.151	CGE0.6101.151	CGL0.6101.151
CG20.6101.151	CG40.6101.151	CGA0.6101.151	CGE0.6133.151	3-126-516
CG26.5101.151	CG46.5101.151	CGC0.6101.151	CGF6.5101.151	

List of part numbers affected for type FKG				
4304.4051				
4304.4052				
4304.4053				
4304.4055				

Product Change Notification					PCN CD/CG/FGK/FKH/FKHD/FKI/FKID/KD/KEB2/K		
owner	creation date	release date	released by	change order	rev	page	D10-064-256
kummerpa	30.03.2022	20.09.2022	muehlema	2024756	A	2 of 4	

List of part numbers affected for type FKH				
4304.4001	4304.4041	4304.4046	4304.4056	3-103-553
4304.4002	4304.4042	4304.4047	4304.4057	
4304.4003	4304.4043	4304.4048	4304.4059	
4304.4004	4304.4044	4304.4049	4304.4060	
4304.4005	4304.4045	4304.4050	4304.4081	

List of part numbers affected for type FKHD				
4304.5001	4304.5031	4304.5040	4304.5045	4304.5050
4304.5002	4304.5036	4304.5041	4304.5046	4304.5052
4304.5003	4304.5037	4304.5042	4304.5047	4304.5053
4304.5004	4304.5038	4304.5043	4304.5048	4304.5054
4304.5005	4304.5039	4304.5044	4304.5049	

List of part numbers affected for type FKI				
4304.4021	4304.4028	4304.4066	4304.4077	4304.4093
4304.4022	4304.4061	4304.4067	4304.4078	4304.4094
4304.4023	4304.4062	4304.4068	4304.4079	4304.4095
4304.4024	4304.4063	4304.4069	4304.4080	
4304.4025	4304.4064	4304.4070	4304.4091	
4304.4027	4304.4065	4304.4076	4304.4092	

List of part numbers affected for type FKID				
4304.5021	4304.5027	4304.5064	4304.5082	4304.5089
4304.5022	4304.5029	4304.5065	4304.5083	4304.5090
4304.5023	4304.5030	4304.5067	4304.5084	
4304.5024	4304.5061	4304.5069	4304.5085	
4304.5025	4304.5062	4304.5073	4304.5086	
4304.5026	4304.5063	4304.5081	4304.5087	

List of part numbers affected for type KD				
KD13.1101.105	KD13.4101.151	KD14.1132.105	KD14.4101.107	KD23.1101.109
KD13.1101.107	KD13.4132.151	KD14.1132.107	KD14.4101.109	KD23.1101.151.1
KD13.1101.109	KD13.4133.151	KD14.1132.151	KD14.4101.151	KD23.4101.151
KD13.1101.151	KD13.4201.151	KD14.1133.105	KD14.4101.307	KD24.1101.105
KD13.1132.105	KD13.4301.107	KD14.1133.107	KD14.4132.105	KD24.1101.107
KD13.1132.107	KD14.1101.105	KD14.1133.109	KD14.4132.109	KD24.1101.109
KD13.1132.151	KD14.1101.107	KD14.1133.151	KD14.4132.151	KD24.1101.151
KD13.1133.107	KD14.1101.107.1	KD14.1201.151	KD14.4133.151	KD90.1002
KD13.1133.151	KD14.1101.109	KD14.1232.107	KD14.4201.151	KD90.1010
KD13.4101.105	KD14.1101.151	KD14.1301.151	KD14.4301.151	KD90.1023
KD13.4101.107	KD14.1101.151.1	KD14.2201.107	KD14.4401.107	KD90.1061
KD13.4101.109	KD14.1101.307	KD14.4101.105	KD14.4401.151	KD90.1136

List of part numbers affected for type KEB2				
4302.2001	4302.2012	4302.2102	4302.2142	4302.3142
4302.2002	4302.2021	4302.2103	4302.2143	4302.8011
4302.2003	4302.2022	4302.2104	4302.2144	4302.8056
4302.2004	4302.2101	4302.2141	4302.3001	4302.3002.01

List of part numbers affected for type KFB2				
4302.5311	4302.5314	4302.5333	4302.5337	
4302.5312	4302.5315	4302.5334	4302.5339	
4302.5313	4302.5331	4302.5335		

List of part numbers affected for type KG				
3-124-652	KG10.6101.151	KG10.8101.151	KG16.5101.151	
KG10.6101.105	KG10.6133.107	KG16.5101.105	KG20.6101.109	
KG10.6101.107	KG10.6133.151	KG16.5101.107	KG26.5101.107	
KG10.6101.109	KG10.7101.151	KG16.5101.109	KG26.5101.161	

Product Change Notification					PCN CD/CG/FGK/FKH/FKHD/FKI/FKID/KD/KEB2/K		
owner	creation date	release date	released by	change order	rev	page	D10-064-256
kummerpa	30.03.2022	20.09.2022	muehlema	2024756	A	3 of 4	

List of part numbers affected for type KP01				
KP01.1112.11	KP01.1112.86	KP01.1152.1190	KP01.1212.1190	KP01.1253.11
KP01.1112.13	KP01.1113.11	KP01.1153.11	KP01.1212.16	KP01.1612.10
KP01.1112.16	KP01.1115.11	KP01.1153.1190	KP01.1213.11	KP01.1752.10
KP01.1112.81	KP01.1152.11	KP01.1212.11	KP01.1252.11	

List of part numbers affected for type 6762				
4304.6049	4304.6055	4304.6060	4304.6071	
4304.6053	4304.6058	4304.6061	4304.6152	
4304.6054	4304.6059	4304.6070	4304.6224	

List of part numbers affected for type 6765				
3-119-110	4304.6079	4304.6088	4304.6094	4304.6192
4304.6073	4304.6080	4304.6089	4304.6095	4304.6207
4304.6074	4304.6081	4304.6090	4304.6123	4304.6215
4304.6075	4304.6082	4304.6091	4304.6149	4304.6266
4304.6076	4304.6083	4304.6092	4304.6153	4304.6192
4304.6077	4304.6087	4304.6093	4304.6178	

Product Change Notification					PCN CD/CG/FGK/FGH/FKHD/FKI/FKID/KD/KEB2/K	
owner	creation date	release date	released by	change order	rev	page
kummerpa	30.03.2022	20.09.2022	muehlema	2024756	A	4 of 4
						D10-064-256