



Expertise Applied | Answers Delivered

PRODUCT CHANGE NOTICE

Issue Date: November 8th, 2022

Dear Valued Customer,

This notice is to inform about a change in one of the finished good(s) you have purchased from Littelfuse.

Description of the Change:

- Littelfuse will move to a new supplier of several components used in the attached Littelfuse finished good(s).

Reason for The Change:

- We will be moving to consolidate suppliers as current supplier is no longer capable to sustain commercial terms.

Effective Date of the Change:

- This will be a running change starting in Q1 2023 and to be completed by Q4 2023.

What You Need to Do:

- No action is required in your behalf. There is no change in product fit, form or function.

If you have any questions, please feel free to contact your Littelfuse Customer Service or Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,

Marian Fernanda Corrales

Associate Product Manager
Littelfuse Commercial Vehicle Products

02980900S
02980900TXN
02980900Z
02981001ZXT
02981002ZXT
02981003ZXT
02981005ZXT
02981012ZXT
02981024ZXT
02981030ZXT
02981034ZXT
02981008ZXT
02981015ZXT
04980900S
04980900ZXT
04980903-BP
04980903ZXT
04980904ZXT
04980905ZXT
04980923ZXT
0498900.TXN
02980900S
02980900TXN
02980900Z
02981001ZXT
02981002ZXT
02981003ZXT
02981005ZXT
02981012ZXT
02981024ZXT
02981030ZXT
02981034ZXT
02981001ZXSS
02981008ZXT
02981015ZXT
04980900S
04980900ZXT
04980902ZXT
04980903-BP
04980903ZXT
04980904ZXT
04980905ZXT
04980923ZXT
0498900.TXN
298907-010
298907-030
02980900S

02980900TXN
02980900Z
02981001ZXT
02981002ZXT
02981003ZXT
02981005ZXT
02981012ZXT
02981014ZXT
02981024ZXT
02981027ZXT
02981030ZXT
02981034ZXT
02981035ZXT
02981039ZXT
02982002ZXT
02982011ZXT
02983006ZXT
02981001ZXSS
02981008ZXT
02981015ZXT
02981036ZXT
02983001ZXFC
02985003ZXFC
02985004ZXFC
04980900S
04980900ZXT
04980902ZXT
04980903-BP
04980903ZXT
04980904ZXT
04980905ZXT
04980908ZXT
04980913ZXT
04980917ZXT
04980923ZXT
0498900.TXN
298907-010
298907-030
02981002ZXSS
02980900S
02980900TXN
02980900Z
02981001ZXT
02981002ZXT
02981003ZXT
02981005ZXT
02981012ZXT

02981014ZXT
02981024ZXT
02981027ZXT
02981030ZXT
02981034ZXT
02981035ZXT
02981039ZXT
02982002ZXT
02982011ZXT
02983006ZXT
CFLEC001Z-01
CFLEC003Z-01
CFLEC003Z-02
CFLEC003Z-03
FLEC0002Z-0
FLEC0014Z-0
FLEC0016Z-0
FLEC0016Z-1
FLEC0018Z-0
FLEC0019Z-0
FLEC0020Z-0
FLEC0020Z-1
FLEC0020Z-2
FLEC0021Z-1
FLEC0021Z-2
FLEC0022Z-01
FLEC0023Z-01
FLEC0025Z-01
FLEC0026Z-01
FLEC0027Z-01
FLEC3000Z-0
FLEC3000Z-0U
02981001ZXSS
02981002ZXSS
02981008ZXT
02981015ZXT
02981036ZXT
02983001ZXFC
02985003ZXFC
02985004ZXFC
04980900S
04980900ZXT
04980902ZXT
04980903-BP
04980903ZXT
04980904ZXT
04980905ZXT

04980908ZXT
04980913ZXT
04980917ZXT
04980923ZXT
04981038-BP
04981038HXFC
04981038HXFC-A
04982001ZXFC
04982002ZXFC
0498900.TXN
298907-010
298907-030
02980900S
02980900TXN
02980900Z
02981001ZXT
02981002ZXT
02981003ZXT
02981005ZXT
02981012ZXT
02981014ZXT
02981024ZXT
02981027ZXT
02981030ZXT
02981034ZXT
02981035ZXT
02981039ZXT
02982002ZXT
02982011ZXT
02983006ZXT
CFLEC001Z-01
CFLEC003Z-01
CFLEC003Z-02
CFLEC003Z-03
FLEC0002Z-0
FLEC0004Z-2
FLEC0004Z-4
FLEC0004Z-7
FLEC0004Z-9
FLEC0010Z-0
FLEC0014Z-0
FLEC0015Z-0
FLEC0016Z-0
FLEC0016Z-1
FLEC0017Z-1
FLEC0017Z-10
FLEC0017Z-11

FLEC0017Z-12
FLEC0017Z-2
FLEC0017Z-3
FLEC0017Z-4
FLEC0017Z-5
FLEC0017Z-6
FLEC0017Z-7
FLEC0017Z-8
FLEC0017Z-9
FLEC0018Z-0
FLEC0019Z-0
FLEC0020Z-0
FLEC0020Z-1
FLEC0020Z-2
FLEC0021Z-1
FLEC0021Z-2
FLEC0022Z-01
FLEC0023Z-01
FLEC0024Z-0
FLEC0025Z-01
FLEC0026Z-01
FLEC0027Z-01
FLEC3000Z-0
FLEC3000Z-0U
LFHCD002Z-01
LFHCD002Z-02
LFHCD002Z-03
LFHCD002Z-04
LFHCD002Z-05
6301
65162
67206
67207
67234
75226
67234-01
75221-09
75221-09-BX
75221-15
75221-18
75226-01
75226-BX
75921-02
75921-03
75921-10