














御中										Issue No. / 発行No: PC-0028782 Issue date / 発行日: 20221213														
<h2 style="text-align: center;">工程変更連絡書</h2> <h3 style="text-align: center;">Process Change Notice</h3>															ヒロセ電機株式会社 東莞工場 品質管理課 Dongguan Factory, Quality control section, Hirose Electric Co., Ltd.									
															承認 (Approval)			査閲 (Review)			作成 (Created by)			
																								
<p>貴社益々ご清栄のこととお喜び申し上げます。日頃は弊社製品のお引き立てを賜り、厚く御礼申し上げます。 早速ですが、貴社への納入製品について、下記の通り工程変更を計画しております。 本書にて工程変更のご案内をさせていただきます。変更計画可否を提出後 2週間以内にご返却を賜りたくお願い致します。 We truly appreciate your significant support always. We are currently planning on the below process change for the products planned to be delivered to your company. Forwarding shares the notification of the process change. Your approval for the change plan within 2 weeks will be appreciated.</p>																								
貴社品番/Product number of your company										弊社品番/Product number by Hirose 0680-1015-0-53					弊社品名/Product name by Hirose DF22-3P-7.92DSA(53)									
Content of change / 変更内容	変更 1	区分 Type	金型の更新 / Die/mold replacement								理由 Reason		金型老朽化の為です / Die/mold age											
	変更 2	区分 Type	-								理由 Reason		-											
	変更前 Before the change								変更後 After the change								影響範囲 The scope that will be affected.							
	日本郡山工場の金型が老朽化しています。 The molds at Koriyama Factory in Japan are aging. →ハウジングの旧金型で生産。 Manufactured with old die of housing.								新金型は中国東莞工場の協力会社で生産されている。 The new mold is produced in the cooperative company of Dongguan factory in China. →ハウジングの旧金型を廃棄して、新型を製作して生産。 The old mold of the housing is abandoned, and the new model is produced and produced.								金型更新に伴い、キャビティ番号とゲート径に変更がありました。製品仕様、性能に影響がありません。詳細は別紙「DF 2 2 製品構造比較」をご覧ください。 There was a change in the cavity number and gate diameter with the mold renewal, but there is no effect on the product specification and performance. For details, please see the "comparison of DF 22 ".							
																	・外観の変更 Appearance 無 No change ・含有物質変更 Containing substance 無 No change							
Execution schedule of the change plan / 変更実施計画	日程 Schedule	12F	12M	12E	1F	1M	1E	2F	2M	2E	3F	3M	3E	4F	4M	4E	5F							
	工程整備 Preparation of process	→																						
	標準類の整備 Preparation of standards, etc.	→																						
	トライ / Trial			→																				
	作業教育 Education on operators				→																			
	製品評価試験 Product evaluation test					→																		
	サンプル提出 Submission of sample						→																	
	初品検査結果提出 Submission of the initial product inspection result							→																
量産納入予定日 Scheduled delivery date of mass production products		2023年 2月予定 Scheduled on 02/2023										備考 Remarks												
変更計画可否回答希望日 Date of your acknowledgement		2022年 12月 27日 27/12/2023																						

ヒロセ電機株式会社 行き To: Hirose Electric Co., Ltd.										Issue No. / 発行No: PC-0028782														
<h3 style="text-align: center;">変更計画可否回答書</h3> Answer to the change plan notification (approval)										製品名 Product name:		DF22-3P-7.92DSA(53)								ご判定日 Judgment day				
										変更内容 Content of change:		金型の更新 / Die/mold replacement								ご担当者 Person in charge				
変更計画可否 Approve or Not approve for the change:										承認 Approved					否認 Not approved					条件付 With condition				
必要提出資料、その他指示事項 Required materials for submission / other directions																								

Comparison of DF22					
DF22-3P-7.92DSA (53)		CLN0:680-1015-0-53			
Mold	Difference	①Cavity	②Gate	③ ~ ⑤ Pin mark	
Current	 	 <div> Cavity NO "K、 L、 M、 N" </div>	 <div> Gate diameter is thick </div>	 <div> With pin marks </div>	
Dongguan New	 	 <div> Cavity NO "P、 Q、 R、 S" </div>	 <div> Gate diameter is thin </div>	 <div> Without pin marks </div>	