

# Information note

**N° 10390AERRA**

**Dear customer,**

With this Infineon Technologies AG information note, we would like to inform you about the following

**HSM\_MEM Release Notes Addendum V3.0 affecting products TC3xx**

**Infineon Technologies AG**

Postal address D-81726 München Internet [www.infineon.com](http://www.infineon.com) Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Wolfgang Eder

Management Board Jochen Hanebeck (CEO), Constanze Hufenbecher, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

# Information note

**N° 10390AERRA**

► **Products affected**

Please refer to attached affected product list  
 “INF\_10390AERRA\_[customer-no].pdf”

► **Detailed change information**

**Subject** HSM\_MEM Release Notes Addendum V3.0 affecting products TC3xx

**Reason** Update of the Release Notes Addendum due to new known issues

**Description**

<u>Old</u>	<u>New</u>
■ Release Notes Addendum Version 2.0	■ Release Notes Addendum Version 3.0

► **Product identification**

Not applicable (no change of product)

► **Impact of change**

Assessment in Application required!

► **Attachments**

INF\_10390AERRA\_[customer-no].pdf affected product list  
 Release Notes Addendum V3.0 – MyICP Link:  
[https://myicp.infineon.com/sites/auto\\_sw/Lists/defaultdoclib/HSM\\_MEM\\_TC3xx/HSM\\_MEM\\_TC3xx/HSM\\_MEM\\_TC3xx\\_Release\\_Notes\\_Addendum\\_v3.0.pdf](https://myicp.infineon.com/sites/auto_sw/Lists/defaultdoclib/HSM_MEM_TC3xx/HSM_MEM_TC3xx/HSM_MEM_TC3xx_Release_Notes_Addendum_v3.0.pdf)

**In case you don't have access, please contact your local Sales/ FAE.**

► **Intended start of delivery**

Not applicable

If you have any questions, please do not hesitate to contact your local sales office.

## ERR 10390AERRA



HSM\_MEM Release Notes Addendum V3.0 affecting products TC3xx

Affected products sold to FUTURE ELECTRONICS INC. (4000624)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC367DP-64F300S AA	SP001694656	TC367DP64F300SAAK XUMA1	PG-LFBGA-292-11	
SAK-TC377TP-96F300S AA	SP001694648	TC377TP96F300SAAK XUMA1	PG-LFBGA-292-11	TC377TP96F300SAAKXU MA1
SAK-TC397XA-256F300S BD	SP005351382	TC397XA256F300SBD KXUMA1	PG-LFBGA-292-12	
SAK-TC397XP-256F300S BC	SP002739600	TC397XP256F300SBC KXUMA1	PG-LFBGA-292-10	TC397XP256F300SBCKX UMA1
SAL-TC377TP-96F300S AA	SP001724092	TC377TP96F300SAAL XUMA1	PG-LFBGA-292-11	

## ERR 10390AERRA



HSM\_MEM Release Notes Addendum V3.0 affecting products TC3xx

Affected products sold to FUTURE ELECTRONICS INC. (4048203)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC364DP-64F300F AA	SP001713956	TC364DP64F300FAAK XUMA1	PG-TQFP-144-27	TC364DP64F300FAAKXU MA, TC364DP64F300FAAKXU MA1

## ERR 10390AERRA



HSM\_MEM Release Notes Addendum V3.0 affecting products TC3xx

Affected products sold to FUTURE ELECTRONICS LTD. (4049887)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC333LP-32F200F AA	SP001724318	TC333LP32F200FAAK XUMA1	PG-TQFP-100-23	
SAK-TC367DP-64F300S AA	SP001694656	TC367DP64F300SAAK XUMA1	PG-LFBGA-292-11	
SAK-TC387QP-160F300S AE	SP005351247	TC387QP160F300SAE KXUMA1	PG-LFBGA-292-11	