

Information note

N° 004/23

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

Amendment of Environmental Flag with/without Change of Ordering Code (OPN# and SP#)

Infineon Technologies AG

Postal address D-81726 München Internet www.infineon.com Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Herbert Diess

Management Board Jochen Hanebeck (CEO), Constanze Hufenbecher, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 12649

Information note

N° 004/23

► **Products affected**

Please refer to attached affected product list
 “INF_004-23_[customer-no].pdf”

► **Detailed change information**

Subject Amendment of Environmental Flag with/without Change of Ordering Code (OPN# and SP#)

Reason To Reflect the Correct Environmental Flag at Production Sites for Each Product

Description	<u>Old</u>		<u>New</u>	
	With SP# and OPN# Change	SP#	OPN#	SP#
	SP001554494	IRF8915TRPBF	SP005876295	IRF8915TRPBFXTMA1
	SP001577432	IRF7303TRPBF	SP005876271	IRF7303TRPBFXTMA1
	SP001565688	IRF9956TRPBF	SP005876297	IRF9956TRPBFXTMA1
	SP001555820	IRF8910TRPBF	SP005876294	IRF8910TRPBFXTMA1
	SP001565270	IRF7328TRPBF	SP005828189	IRF7328TRPBFXTMA1
	SP001565328	IRF7201TRPBF	SP005876270	IRF7201TRPBFXTMA1
	SP001575370	IRF9910TRPBF	SP005876296	IRF9910TRPBFXTMA1
	SP001555342	IRF7413ZTRPBF	SP005876278	IRF7413ZTRPBFXTMA1
	SP001554204	IRF7341TRPBF	SP005876277	IRF7341TRPBFXTMA1
	SP001562004	IRF7103TRPBF	SP005876269	IRF7103TRPBFXTMA1
	SP001577624	IRF8721TRPBF	SP005876290	IRF8721TRPBFXTMA1
	SP001563692	IRF7805ZTRPBF	SP005876285	IRF7805ZTRPBFXTMA1
	SP001562160	IRF7313TRPBF	SP005876276	IRF7313TRPBFXTMA1
	SP001577632	IRF8714TRPBF	SP005876289	IRF8714TRPBFXTMA1
	SP001577448	IRF7821TRPBF	SP005876287	IRF7821TRPBFXTMA1
	*SP001570892	IRFHM8326TRPBF	*SP005876303	IRFHM8326TRPBFXTMA1
Without SP# and OPN# Change	SP#	OPN#	SP#	OPN#
	SP001557678	IRFU120NPBF	SP001557678	IRFU120NPBF
	SP001578380	IRFU3910PBF	SP001578380	IRFU3910PBF
	SP001567330	IRLU120NPBF	SP001567330	IRLU120NPBF
	SP001574164	IRLU3410PBF	SP001574164	IRLU3410PBF
	SP001553260	IRLU024NPBF	SP001553260	IRLU024NPBF
	SP001570224	IRF7314TRPBF	SP001570224	IRF7314TRPBF
	SP001555914	IRF9952TRPBF	SP001555914	IRF9952TRPBF
Product Barcode Label	Without Halogen Free Flag Logo		With Halogen Free Flag Logo	
	*Only SP001570892 has Halogen Free Flag present		*SP005876303 created due to Completely Pb Free Flag update from N to Y, no change in label	

Information note

N° 004/23

▶ **Product identification**

Products to be identified via OPN#, SP#, Product Barcode Label

▶ **Impact of change**

No Impact on Electrical Performance of the Products

▶ **Attachments**

INF_004-23_*[customer-no]*.pdf affected product list

▶ **Intended start of delivery**

Immediate

If you have any questions, please do not hesitate to contact your local sales office.