



# Product Change Notification

Current Date: 20-Mar-2023

## TE Connectivity

Product Change Notification: P-23-024236

PCN Date: 10-MAR-23

Customer: DISTRIBUTOR EMEA ( 66666663 )

Location: NO CITY PROVIDED

Agreement: 120513160001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Polamco brand Backshells and accessories

### Description of Changes

Second source qualification. Following Part Numbers are being approved to be manufactured at an outside vendor.

### Reason for Changes:

Dear Customer, as a result of our continuous strive to aid our lead-time recovery initiative, we hereby inform you about the use of a second source for components used in these products, the secondary operations remain as today. The qualification is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The second manufacturing location is under a certified quality management system according to standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	08-MAY-2023
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">034125-000</a>	NO			2-1190264-8, 202M710-19C			
<a href="#">76H1-15-1-B</a>	NO						
<a href="#">76H1-15-1-C</a>	NO						
<a href="#">76H1-15-1-ZB</a>	NO						
<a href="#">76H1-15-1-ZN</a>	NO						
<a href="#">800892-000</a>	NO			7-1200074-8, TX40AB00-2410H			
<a href="#">91H1-19-16-1-ZN</a>	NO						
<a href="#">99R1-12-1-ZB</a>	NO						
<a href="#">AAA5212-00</a>	NO			39H1-09-12-1-B-NE-CC-L4			
<a href="#">AAA5249-00</a>	NO			39H1-13-12-1-B-NE-CC-L4			
<a href="#">AAA5309-00</a>	NO			39H1-17-12-1-B-NE-CC-L3			
<a href="#">AAB0008-00</a>	NO			91F1-19-10-1-B-HE200			
<a href="#">AAB0010-00</a>	NO			91F1-19-10-1-ZB-HE200			
<a href="#">AAB2208-00</a>	NO			91H1-19-16-1-B-HE300			
<a href="#">AAB2210-00</a>	NO			91H1-19-16-1-C-HE300			
<a href="#">AAB2211-00</a>	NO			91H1-19-16-1-ZB-HE300			
<a href="#">AAB2503-00</a>	NO			91H1-25-06-1-ZB-L40-HE100			
<a href="#">AAB4344-00</a>	NO			91M1-18-10-1-B-HE200			
<a href="#">AAB4370-00</a>	NO			91M1-20-15-1-B-L50-HE300			
<a href="#">AAB4408-00</a>	NO			91M2-18-11-1-B-HE200			
<a href="#">AAB4409-00</a>	NO			91M2-18-19-1-B-HE400			
<a href="#">AAB6009-00</a>	NO			APA1-14-10-15-1-B-AD			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">AAB6299-00</a>	NO			APLC1-14-M20-80-1-C			
<a href="#">AAC5062-00</a>	NO			APLC1-14-M20-15-1-C			
<a href="#">AAE0970-00</a>	NO			91H1-19-16-1-ZN-HE300			
<a href="#">AAE2512-00</a>	NO			98H1-19-1-ZN-AD			
<a href="#">AAE4625-00</a>	NO			BTM1-18-04-1-C			
<a href="#">APH1-15-14-25-1-B</a>	NO						
<a href="#">APH1-15-14-25-1-C</a>	NO						
<a href="#">BAEQ564-00</a>	NO			APLC1-14-M25-30-1-C			
<a href="#">BTF1-18-16-1-B-SB</a>	NO						
<a href="#">BTF1-19-10-1-C</a>	NO						
<a href="#">BTH1-17-16-1-B-L38</a>	NO						
<a href="#">BTH1-19-16-1-B</a>	NO						
<a href="#">BTH1-19-16-1-B-SB</a>	NO						
<a href="#">BTH1-19-16-1-C</a>	NO						
<a href="#">BTH1-19-16-1-C-SB</a>	NO						
<a href="#">BTH1-19-16-1-ZB</a>	NO						
<a href="#">BTH1-19-16-1-ZB-SB</a>	NO						
<a href="#">BTH1-19-16-1-ZN</a>	NO						
<a href="#">BTH1-19-16-1-ZN-SB</a>	NO						
<a href="#">BTH1-19-20-1-C</a>	NO						
<a href="#">BTH1-19-20-1-ZN-SB</a>	NO						
<a href="#">BTM1-18-06-1-C</a>	NO						
<a href="#">BTM1-18-08-1-C</a>	NO						
<a href="#">BTM1-18-10-1-C</a>	NO						
<a href="#">BTM1-18-12-1-C</a>	NO						
<a href="#">BTM1-18-14-1-C</a>	NO						
<a href="#">C36837-000</a>	NO			3-1201144-6, TXR40SJ00-1405AI			
<a href="#">C42474-000</a>	NO			5-1201103-3, 209M312-62J			
<a href="#">C80368-000</a>	NO			6-1199629-4, TXR66AB00-1104AI			
<a href="#">CM2132-000</a>	NO			TX40AB00-1207H			
<a href="#">CY6655-000</a>	NO			TX40AB00-1206H			
<a href="#">CZ6255-000</a>	NO			TX40AB00-0806H			
<a href="#">EL6495-000</a>	NO			TX47AB00-1810			
<a href="#">F01921-000</a>	NO			4-1200362-8, TX40AB00-1408H			
<a href="#">F75852-000</a>	NO			8-1200133-2, TX40AB00-2012H			