



KYOCERA AVX Components Corporation

1 AVX Boulevard  
 Fountain Inn, SC 29644 USA  
 Phone: +1 (864) 967-2150  
 Website: <https://www.kyocera-avx.com>

Attention:

Future Electronics

## Change Notice

Dear Valued Customer,

In order to increase capacity Kyocera AVX wish to provide notification of the plan to introduce the Kyocera AVX facility in Nakhon Ratchasima, Thailand as an additional manufacturing location for MLCC. Plant target to be IATF16949 compliant by 1st April 2023.

1. Product Type, Changes, and Customer/AVX/Alternate Part Numbers:

Change	Current Manufacturing Sites	After Change
Additional Manufacturing facility for MLCC	Penang, Malaysia, San Salvador, El Salvador Coleraine, UK Kokubu, Japan	Penang, Malaysia, San Salvador, El Salvador Coleraine, UK Kokubu, Japan Nakhon Ratchasima, Thailand

Components covered by this PCN

<b>MLCC Automotive Range:</b> <b>PN with 11th digit = "4"</b> e.g. 06035C104K4T2A <b>Or New PN 2nd digit = "A"</b> e.g. KAM15AR71H104KT		
Case	Voltage	Cap Range
0603	16-50V	273-104
0805	16-25V	474-225
	50V	104-105
	100V	104-106
FS05	16-100V	682-104
1206	25-50V	684-475
	100V	124-225



KYOCERA AVX Components Corporation

1 AVX Boulevard  
Fountain Inn, SC 29644 USA  
Phone: +1 (864) 967-2150  
Website: <https://www.kyocera-avx.com>

Future Electronics

2. Reasons/Background:

Kyocera AVX is expanding MLCC operations.

3. Products Before and After the Change:

Samples available now.

4. Change Schedule:

Change Event	Target Completion Date	Comments
Production Start	July 1, 2023	

5. Feedback Due:

**July 1, 2023**

Please indicate your feedback to Kyocera AVX in writing by this feedback date.

6. Contact:

Should you have any questions or concerns, please contact

US, Zack Kozawa, [zack.kozawa @kyocera-avx.com](mailto:zack.kozawa@kyocera-avx.com)

Thank you.

March 14, 2023



KYOCERA AVX Components Corporation

1 AVX Boulevard  
Fountain Inn, SC 29644 USA  
Phone: +1 (864) 967-2150  
Website: <https://www.kyocera-avx.com>

**Automotive**

**Customer feedback regarding the change notification:**

Requests, Questions, Comments:

--

<b>Signature of Approval</b>	
<b>Date</b>	
<b>Title</b>	
<b>Name</b>	
<b>Company Name</b>	

AFFECTED PART NUMBERS

08053C105J4T2A  
08055C105K4T2A  
08055C105K4Z2A  
08055C474K4Z4A  
12061C105J4T2A  
12061C105K4T2A  
12061C105K4Z2A  
12063C185K4Z2A  
12063C225K4T2A  
12063C225KAT2A  
12065C105M4T2A  
12065C225K4T2A  
12101C105K4T2A  
12101C105K4Z2A  
12101C225K4Z2A  
12101C225K4Z4A  
12101C474K4T2A  
12103C105K4Z2A  
12103C106K4T2A  
12103C106K4Z2A  
12105C105K4T2A  
12105C335K4T2A  
12105C335KAT2A  
12105C475K4T2A  
12105C475K4T4A  
12105C475K4Z2A  
12105C475M4T2A  
18123D106KAT2A  
18125C475MAT2A  
1812ZD226KAT2A  
22203C226KAT2A  
22203C226KAZ2A  
22205C106K4Z2A  
FS055C103K4Z2A  
FS105C224K4Z4A  
LD061C105KAB2A  
08051C105K4T2A  
08051C105K4Z2A  
08051C224K4Z2A  
08051C474K4T2A  
08051C474K4T4A  
08051C474K4Z2A  
08051C474KAZ2A  
08053C105K4T2A  
08055C105K4T2A  
08055C105K4Z2A  
08055C474K4T2A  
08055C474K4Z2A  
08055C474M4Z2A  
12061C105K4T2A  
12061C105K4Z2A  
12061C105K4Z4A  
12061C225K4T2A  
12061C225KAT2A  
12063C185K4Z2A  
12063C225KAT2A  
12065C105K4Z2A  
12065C225K4T2A  
12065C475K4T2A  
12065C475K4Z2A

1206ZD475KAT2A  
12101C105K4Z2A  
12101C475K4T2A  
12101C475K4Z2A  
12101C475KAT2A  
12103C105K4Z2A  
12103C106K4T2A  
12103C106K4Z2A  
12105C106K4T2A  
12105C106K4Z2A  
12105C225K4T2A  
12105C335KAT2A  
12105C475K4T2A  
12105C475K4Z2A  
12105C475KAT4A  
12105C475M4Z2A  
1210YC475K4T2A  
1210YC475K4Z2A  
18121C225K4Z2A  
18123D106KAT2A  
18123D106MAT2A  
18125C475K4Z2A  
1812ZD226KAT2A  
22201C106K4Z2A  
22201C475K4Z2A  
22203C226KAT2A  
22203C226MAT2A  
FS055C104K4Z2A  
FS055C223K4Z2A  
FS105C224K4Z2A  
FS105C224K4Z4A  
FS105C474K4Z4A  
08051C105K4T2A  
08051C105K4Z2A  
08051C224K4T2A  
08051C224K4Z2A  
08051C334K4Z2A  
08051C474K4T2A  
08051C474K4T4A  
08051C474K4Z2A  
08051C474KAZ2A  
08053C105J4T2A  
08053C105K4T2A  
08053C105K4Z2A  
08053C105K4Z4A  
08053C225K4T2A  
08053C225K4Z2A  
08053C684K4T2A  
08055C105K4T2A  
08055C105K4Z2A  
08055C334K4T2A  
08055C334K4Z2A  
08055C334KAT2A  
08055C474K4T2A  
08055C474K4Z2A  
08055C474K4Z4A  
08055C474M4Z2A  
0805YC105K4T2A  
0805YC105K4Z2A  
0805YC824KAT2A  
12061C105J4T2A

12061C105K4T2A  
12061C105K4Z2A  
12061C105K4Z4A  
12061C224K4Z2A  
12061C334K4Z2A  
12061C474K4Z2A  
12063C185K4Z2A  
12063C225K4T2A  
12063C225KAT2A  
12063C475K4T2A  
12065C105J4T2A  
12065C105K4T2A  
12065C105K4Z2A  
12065C475K4T2A  
12101C105K4T2A  
12101C105K4Z2A  
12101C225K4T2A  
12101C225K4T4A  
12101C225K4Z2A  
12101C225K4Z4A  
12101C225KAT2A  
12101C474K4T2A  
12101C475K4T2A  
12103C105K4Z2A  
12103C106K4T2A  
12105C105JAT2A  
12105C105K4T2A  
12105C105K4Z2A  
12105C106K4T2A  
12105C106K4Z2A  
12105C106KAT2A  
12105C106KAT2A\500  
12105C225K4T2A  
12105C335K4T2A  
12105C335KAZ2A  
12105C475K4T2A  
12105C475K4T4A  
12105C475K4Z2A  
12105C475KAT4A  
12105C475KHZ2A  
12105C475M4T2A  
12105C475M4Z2A  
1210DC106KAT2A  
1210YC475K4T2A  
1210YC475K4Z2A  
22201C685K4T2A  
22203C226KAT2A  
22203C226MAT2A  
AU05YC474KA76A  
FS055C104K4Z2A  
FS055C223K4Z2A  
FS105C334K4Z4A  
FS105C474K4Z4A  
LD053C105KAB2A  
LD061C105KAB2A  
LD105C106KAB2A\500