

Information note

N° 10409AERRA

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

MC-ISAR AURIX AS4xx Release Notes Addendum V13.0 affecting products TC3xx

Infineon Technologies AG

Postal address D-81726 München Internet www.infineon.com Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Herbert Diess

Management Board Jochen Hanebeck (CEO), Constanze Hufenbecher, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg

Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

Information note

N° 10409AERRA

▶ **Products affected**

Please refer to attached affected product list
 “INF_10409AERRA_[customer-no].pdf”

▶ **Detailed change information**

Subject MC-ISAR_AS4xx_TC3xx Release Notes Addendum, V13.0.

Reason Update of the release notes addendum due to new known issues.

Description

<u>Old</u>	<u>New</u>
■ Release Notes Addendum Version 12.0	■ Release Notes Addendum Version 13.0

▶ **Product identification**

Not applicable (no change of product)

▶ **Impact of change**

Assessment in Application required!

▶ **Attachments**

INF_10409AERRA_[customer-no].pdf affected product list
 Release Notes Addendum V13.0
 MyICP Link:
https://myicp.infineon.com/sites/auto_sw/Lists/defaultdoclib/MC-ISAR%20AURIX2G/MC-ISAR%20AS422%20Aurix2G%20Addendum/MC-ISAR_AS4xx_TC3xx_Release_Notes_Addendum_v13.0.pdf

In case you don't have access, please contact your local Sales/FAE.

▶ **Intended start of delivery**

Not applicable

If you have any questions, please do not hesitate to contact your local sales office.

ERR 10409AERRA



MC-ISAR AURIX AS4xx Release Notes Addendum V13.0 affecting products TC3xx

Affected products sold to FUTURE ELECTRONICS LTD. (4049887)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC333LP-32F200F AA	SP001724318	TC333LP32F200FAAK XUMA1	PG-TQFP-100-23	
SAK-TC367DP-64F300S AA	SP001694656	TC367DP64F300SAAK XUMA1	PG-LFBGA-292-11	
SAK-TC387QP-160F300S AE	SP005351247	TC387QP160F300SAE KXUMA1	PG-LFBGA-292-11	

ERR 10409AERRA



MC-ISAR AURIX AS4xx Release Notes Addendum V13.0 affecting products TC3xx

Affected products sold to FUTURE ELECTRONICS INC. (4048203)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC364DP-64F300F AA	SP001713956	TC364DP64F300FAAKXUMA1	PG-TQFP-144-27	TC364DP64F300FAAKXUMA, TC364DP64F300FAAKXUMA1
SAK-TC397XA-256F300S BD	SP005351382	TC397XA256F300SBDKXUMA1	PG-LFBGA-292-12	TC397XA256F300SBDKXUMA1

ERR 10409AERRA



MC-ISAR AURIX AS4xx Release Notes Addendum V13.0 affecting products TC3xx

Affected products sold to FUTURE ELECTRONICS INC. (4000624)

Sales name	SP number	OPN	Package	Customer part number
SAK-TC367DP-64F300S AA	SP001694656	TC367DP64F300SAAKXUMA1	PG-LFBGA-292-11	
SAK-TC377TP-96F300S AA	SP001694648	TC377TP96F300SAAKXUMA1	PG-LFBGA-292-11	TC377TP96F300SAAKXUMA1
SAK-TC397XA-256F300S BD	SP005351382	TC397XA256F300SBDKXUMA1	PG-LFBGA-292-12	
SAK-TC397XP-256F300S BC	SP002739600	TC397XP256F300SBCKXUMA1	PG-LFBGA-292-10	TC397XP256F300SBCKXUMA1
SAK-TC397XP-256F300S BD	SP005351385	TC397XP256F300SBDKXUMA1	PG-LFBGA-292-10	
SAL-TC364DP-64F300F AA	SP001724134	TC364DP64F300FAALXUMA1	PG-TQFP-144-27	
SAL-TC377TP-96F300S AA	SP001724092	TC377TP96F300SAALXUMA1	PG-LFBGA-292-11	TC377TP96F300SAALXUMA1