

# Product Discontinuation



## PD\_016\_21

■ Last Order Date:	2021-08-15
■ Last Delivery Date:	2022-02-15

Reason: Product is /products are being replaced by succeeding generation (or by a new package generation or by a new technology)

DISCONTINUED				NEW (REPLACEMENT)			
Sales Name	SP Number	OPN	Package	Sales Name	SP Number	OPN	Package
TLI4970-D025T4	SP001323154	TLI4970D025T4XUMA1	PG-TISON-8	TLI4971-A025T5-U-E0001	SP005446646	TLI4971A025T5UE0001XUMA1	PG-TISON-8
TLI4970-D025T5	SP001323150	TLI4970D025T5XUMA1	PG-TISON-8	TLI4971-A025T5-U-E0001	SP005446646	TLI4971A025T5UE0001XUMA1	PG-TISON-8
TLI4970-D050T4	SP000917088	TLI4970D050T4XUMA1	PG-TISON-8	TLI4971-A050T5-U-E0001	SP005446651	TLI4971A050T5UE0001XUMA1	PG-TISON-8
TLI4970-D050T5	SP001323146	TLI4970D050T5XUMA1	PG-TISON-8	TLI4971-A050T5-U-E0001	SP005446651	TLI4971A050T5UE0001XUMA1	PG-TISON-8

If you have any questions, please do not hesitate to contact your local sales office.

**Disclaimer:** The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.