



## Product Change Notification / MFOL-24SJQF382

---

### Date:

27-Apr-2022

### Product Category:

Bluetooth Module, Wireless Modules

### PCN Type:

End of Life

### Notification Subject:

eSign# E000104918: End of Life (EOL) of RN41xx, RN-27xx, RN42xx, RN52xx and RN-24xx device families.

### Affected CPNs:

[MFOL-24SJQF382\\_Affected\\_CPN\\_04272022.pdf](#)  
[MFOL-24SJQF382\\_Affected\\_CPN\\_04272022.csv](#)

### Notification Text:

**PCN Status:**End of Life (EOL) Notification

**Microchip Parts Affected:**Please open one of the files found in the Affected CPNs section.

The list of affected CPNs with its corresponding replacement parts (if applicable) can be found on the attachments field labeled as PCN\_#\_Suggested Replacements.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

**EOL Description:**The RN41xx, RN-27xx, RN42xx, RN52xx and RN-24xx device families will be moving to End of Life (EOL) status effective today. These device families will no longer be offered after the date listed in the attached PCN\_#\_Suggested\_Replacements file. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your **Local Sales Representative**

**Reason for EOL:**No longer have manufacturing support for the CPN listed in the attachment.

**Estimated Effective Dates:**Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

Last date for bookings (LTB): Please refer to PCN\_#\_Suggested\_Replacements (excel file) for the list of LTB dates identified per catalog part number.

Last date for shipments (LTS): Please refer to PCN\_#\_Suggested\_Replacements (excel file) for the list of LTS dates identified per catalog part number.

**Revision History:**April 27, 2022: Issued EOL notification.

## **Attachments:**

[PCN\\_MFOL-24SJQF382\\_Suggested Replacements.xlsx](#)  
[PCN\\_MFOL-24SJQF382\\_Suggested Replacements.pdf](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

**PCN\_PCN\_MFOL-24SJQF382**

| <b>EOL Catalog Part Number (CPN)</b> | <b>Recommended Replacement</b> | <b>Last date for purchase (LTB)</b> | <b>Last date for shipments (LTS)</b> | <b>Notes about Recommended Replacement Parts</b> |
|--------------------------------------|--------------------------------|-------------------------------------|--------------------------------------|--|
| RN41NAPL-I/RM545                     | RN4678APL-V/RM122              | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-270FDTV                           | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-270MGDC010                        | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42NAPL-I/RM545                     | RN4678APL-V/RM122              | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42NHCI-I/RM                        | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN52CVC-I/RM116                      | BM83SM1-00AB                   | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42NHID-I/RM                        | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-270FGDC010                        | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN52SRC-I/RM100                      | BM83SM1-00AB                   | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-270F                              | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42-I/RMCOS477                      | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN52UDF-I/RM116                      | BM83SM1-00AB                   | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN52APC-I/RM117                      | BM83SM1-00AB                   | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42N-I/RMCOS477                     | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42NU-I/RM                          | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-270M                              | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-240FGDC010                        | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42U-I/RM                           | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-240MGDC010                        | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42NAPL-I/RM                        | RN4678APL-V/RM122              | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-240M                              | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN42-I/RMEVO519                      | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN-240F                              | RN4678-V/RM122                 | April 27, 2022                      | April 27, 2022                       | <a href="#">Contact Your Local Sales Office</a>  |
| RN41NAPL-I/RM543                     | RN4678APL-V/RM122              | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN41N-I/RM615                        | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN41N-I/RM477                        | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN41NAPL-I/RM                        | RN4678APL-V/RM122              | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN41N-I/RM                           | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42XVU-I/RM                         | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42SM-I/RM                          | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42-I/RMMGK477                      | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42N-I/RM477                        | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN52-I/RM110                         | BM83SM1-00AB                   | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42-I/RMETI540                      | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42HCI-I/RM                         | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42APL-I/RM                         | RN4678APL-V/RM122              | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42HID-I/RM                         | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42N-I/RM                           | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42-I/RM477                         | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42-I/RM615                         | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42-I/RM630                         | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42APL-I/RM543                      | RN4678APL-V/RM122              | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42APL-I/RM545                      | RN4678APL-V/RM122              | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42-I/RM                            | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42APL-I/RM550                      | RN4678APL-V/RM122              | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN42XVP-I/RM                         | RN4678-V/RM122                 | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |
| RN52-I/RM                            | BM83SM1-00AB                   | April 27, 2023                      | August 27, 2023                      | <a href="#">Contact Your Local Sales Office</a>  |

Affected Catalog Part Numbers (CPN)

RN41NAPL-I/RM545  
RN-270FDTV  
RN-270MGDC010  
RN42NAPL-I/RM545  
RN42NHCI-I/RM  
RN52CVC-I/RM116  
RN42NHID-I/RM  
RN-270FGDC010  
RN52SRC-I/RM100  
RN-270F  
RN42-I/RMCOS477  
RN52UDF-I/RM116  
RN52APC-I/RM117  
RN42N-I/RMCOS477  
RN42NU-I/RM  
RN-270M  
RN-240FGDC010  
RN42U-I/RM  
RN-240MGDC010  
RN42NAPL-I/RM  
RN-240M  
RN42-I/RMEVO519  
RN-240F  
RN41NAPL-I/RM543  
RN41N-I/RM615  
RN41N-I/RM477  
RN41NAPL-I/RM  
RN41N-I/RM  
RN42XVU-I/RM  
RN42SM-I/RM  
RN42-I/RMMGK477  
RN42N-I/RM477  
RN52-I/RM110  
RN42-I/RMETI540  
RN42HCI-I/RM  
RN42APL-I/RM  
RN42HID-I/RM  
RN42N-I/RM  
RN42-I/RM477  
RN42-I/RM615  
RN42-I/RM630  
RN42APL-I/RM543  
RN42APL-I/RM545  
RN42-I/RM  
RN42APL-I/RM550  
RN42XVP-I/RM

RN52-I/RM